



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101119

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 22/02/2021
Reference CC4/FCI20011700/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMG 5298J
Insured Veh. SHA 9506Z
Claim No. D20004354MFSH
Policy No. D-18088937MFSH
Accident Date 26/10/2020
Inspection Date 28/10/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20011700/R1ra3q2	
			Date: 22/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 9506Z	Veh. Inspected	SMG 5298J
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D20004354MFSH	Excess (\$)	0.00
	Assign From	ERIC	Assign Date	27/10/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA HRV 1.5 LX CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JHMRU1830JX200889	Colour	BLACK
	Odometer	158024 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	DUNLOP	6 mm
	L/H Front Tyre	215/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/10/2020	Inspection Date	28/10/2020
	Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 5298J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL GATE COMP (SN)	BENT	658.42	641.77
1	WEATHERSTRIP TAILGATE (SN)	SERVICEABLE	75.97	-
1	LOCK ASSY ,TAILGATE ASSY (SN)	SERVICEABLE	125.55	-
1	EMBLEMRR (SN)	NECESSARY	10.95	10.95
1	EMBLEM,RR.I-VTEC (SN)	NECESSARY	11.92	11.92
1	FACE ,RR BUMPER (SN)	DEFORMED	347.77	347.77
1	FACE ,R.RR.BUMPER CORNER (SN)	SERVICEABLE	72.37	-
1	FACE ,L.RR.BUMPER CORNER (SN)	SERVICEABLE	72.37	-
1	REFLECTOR ASSYR.RR. (SN)	SERVICEABLE	128.10	-
1	REFLECTOR ASSYL.RR. (SN)	SERVICEABLE	128.10	-
1	SPACER ,R.RR.BUMPER SIDE (SN)	NECESSARY	12.97	12.97
1	SPACER,L.RR.BPR S (SN)	NECESSARY	12.97	12.97
8	CLIP,BUMPER (SN)	NECESSARY	13.80	13.80
1	PANEL COMPRR (SN)	SERVICEABLE	287.02	-
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	33.75	-
1	LIGHT ASSY,R.LID (SN)	SERVICEABLE	207.67	-
1	LIGHT ASSY,L.LID (SN)	SERVICEABLE	207.67	-
1	LAMP UNIT,R (SN)	SERVICEABLE	309.00	-
1	LAMP UNIT,L (SN)	SERVICEABLE	309.00	-
1	RUBBER CR.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	DAMPERSTD 5X5 (SN)	NECESSARY	6.52	6.52
1	RUBBER CL.WINDSHIELD DAMPER (SN)	NECESSARY	14.47	14.47
1	CAPPIVOT (SN)	NECESSARY	3.75	3.75
4	FASTENER BW/SHIELD (SN)	NECESSARY	15.90	15.90
2	FASTENER B (SN)	NECESSARY	7.95	7.95
2	FASTENER AW/SHIELD (SN)	NECESSARY	5.70	5.70
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00
4	PCS ACT RR.SENSOR (SN)	SERVICEABLE	320.00	-
1	NUMBER PLATE WITH CASING-L (SN)	SERVICEABLE	45.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	50.00

Report Ref No. CC4/FCI20011700/R1ra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	GROMMET SCREW (SN) (ADDITIONAL)	NECESSARY	3.60	3.60
			3,682.73	1,294.51
	LABOUR			
	BODY JOINT SEALANT .		120.00	120.00
	INSPECT RR LIGHTING MECHANISMS PERFORM WATER .		280.00	250.00
	REMOVE & RENEW REVERSE SENSORS.		280.00	250.00
	RESET VEHICLE SMART ENTRY SYSTEM.		560.00	480.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		560.00	480.00
	REMOVED & TRANSFER ITEMS TO NEW TAILGATE ADJUST & .		650.00	325.00
	REPLACE RR.WINDSCREEN .		650.00	650.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		650.00	325.00
	CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN .		5,200.00	1,300.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,640.00	1,560.00
	BODY UNDERSIDE COATING .		350.00	250.00
			12,940.00	5,990.00
GRAND TOTAL			16,622.73	7,284.51
RECOMMENDED COST OF REPAIRS				7,284.51

Report Ref No. CC4/FCI20011700/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 5298J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 5298J

RE-INSPECTION

