

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20011707/KBA3Q2

Date: 16/02/2021

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SHC5678B	<b>Insured Vehicle No :</b>	SHC8184P
Date of Loss:	22/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100384

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHC5678B</b>		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002154
Reg. Date:	04/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC279839
Colour:	Metallic White/Red	Odometer:	628101 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,597.42	1,041.24	4,556.18	81.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	480.00	7,100.00	93.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,177.42</b>	<b>1,521.24</b>	<b>11,656.18</b>	<b>88.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
(S\$)	13,177.42	1,200.00	11,977.42	90.89
<b>+ GST 7.00/7.00% (S\$)</b>	922.42	84.00	838.42	90.89
<b>Nett Amount (S\$)</b>	<b>14,099.84</b>	<b>1,284.00</b>	<b>12,815.84</b>	<b>90.89</b>
<b>+ Loss of Use (2.0 x S\$50.00/day) (S\$)</b>		100.00		
<b>+ Car Rental (2.0 x S\$81.13/day) (S\$)</b>		162.26		
<b>Nett Liability (S\$)</b>		<b>1,546.26</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,500.00</b>		

### INSPECTION

Date of Assignment:	26/10/2020		
Date Inspected:	26/10/2020	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Jan 2021)

**Parts:** 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHC5678B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Cracked	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*OUTER PANEL REAR (END PANEL )	Repair	745.80 FL	*- FL
12	1		*OUTER PANEL REAR (END PANEL )TRIM	Serviceable	404.56 FL	*- FL
13	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
14	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
15	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
16	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
17	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
18	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
19	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
20	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
21	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
22	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
23	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
24	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
25	1		*REAR BOOT STICKER TRASN-CAB	Not Necessary	80.00 FS	*- FS
26	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,094.38</b>	<b>1,138.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	496.96	97.36
<b>Total Parts (\$\$)</b>	<b>5,597.42</b>	<b>1,041.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,580.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >