

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20011711/AGS3Q2
Date: 15/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SGP3774M	Insured Vehicle No :	SHC1005U
Date of Loss:	26/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100419

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP3774M		
Make & Model:	TOYOTA FORTUNER, 2.4 G DSL (A)	Engine No:	2TR6321089
Reg. Date:	14/12/2006 (Man. Year: 2006)	Chassis No:	MR0YX59G500011430
Colour:	Black	Odometer:	150695 km
Engine Capacity:	2694 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	265/70 R16	Rear Tyre Size:	265/70 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,519.60	2,432.45	3,087.15	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,310.00	1,150.00	46.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,979.60	3,742.45	4,237.15	53.10
Approved Total (Overridden) (S\$)		2,900.00		

(S\$)	7,979.60	2,900.00	5,079.60	63.66
+ GST 7.00/7.00% (S\$)	558.57	203.00	355.57	63.66
Nett Amount (S\$)	8,538.17	3,103.00	5,435.17	63.66
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,532.00		

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 27/10/2020

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	192	TOYOTA FORTUNER 2.4 G DSL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP3774M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Not Necessary	630.00 FL	*- FL
2	1		*FRONT FENDER EMBLEM LH	Not Necessary	88.90 FL	*- FL
3	1		*FRONT FENDER PROTECTOR LH	Deformed	480.00 FL	*365.00 FL
4	1		*FRONT DOOR LH	Dented	1,588.30 FL	*1,496.00 FL
5	1		*FRONT DOOR POWER WINDOW MOTOR	Not Necessary	580.00 FL	*- FL
6	1		*FRONT DOOR POWER WINDOW REGULATION	Damaged	355.60 FL	*355.60 FL
7	1		*ROCKER PANEL LH	Repair	890.00 FL	*- FL
8	1		*FRONT FENDER PROTECTOR SEALANT	Necessary	80.00 FS	*20.00 FS
9	1		*SUN VISOR	Necessary	180.00 FS	*100.00 FS
10	1		*STEP PANEL	Bent	1,800.00 FS	*650.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,672.80	2,986.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,153.20	554.15
Total Parts (\$\$)	5,519.60	2,432.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,000.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	600.00
3	MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
4	WIRING CHECK	New	100.00	30.00
5	TO REMOVE AND REFIX FRONT DOOR MECHANISM	New	180.00	80.00
Gross Labour Cost (S\$)			2,460.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >