



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5956G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	420.00	-
1	FRONT BUMPER LH RETAINER	NOT NECESSARY	38.00	-
1	LH MIRROR COVER	TO REPAIR SEE LABOUR	185.00	-
1	LH MIRROR ASSEMBLY	NOT NECESSARY	620.00	-
1	LH FRT DOOR ASSY	TO REPAIR SEE LABOUR	866.00	-
1	LH REAR DOOR ASSY	BUCKLED	856.00	856.00
1	LH REAR WINDOW PWR MOTOR UNIT	NOT NECESSARY	335.00	-
1	LH SIDE SKIRT	TO REPAIR SEE LABOUR	1,175.00	-
1	LH QUARTER PANEL ASSY	TO REPAIR SEE LABOUR	1,275.00	-
1	REAR BUMPER LH RETAINER	NOT NECESSARY	38.00	-
1	SET LH FRONT DOOR SEAL	NOT NECESSARY	85.00	-
1	SET LH REAR DOOR SEAL	NOT NECESSARY	85.00	-
	LESS 20% DISCOUNT		-	-171.20
			5,978.00	684.80
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT DOOR PANEL CLIPS / FASTENERS (SN)	NOT NECESSARY	60.00	-
1	SET REAR DOOR PANEL CLIPS / FASTENERS (SN)	NECESSARY	60.00	30.00
1	SET FRONT WHEEL ARCH COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR WHEEL ARCH COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET SIDE SKIRT CLIPS FASTENERS (SN)	NOT NECESSARY	60.00	-
			300.00	30.00
<u>LABOUR</u>				
	PANEL BEATING AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER, LH MIRROR COVER, LH FRT DOOR ASSY, LH SIDE SKIRT AND LH QUARTER PANEL ASSY.		1,200.00	400.00
	SPRAY PAINTING AFFECTED AREAS.		1,600.00	1,100.00
	CHECK WIRING.		120.00	30.00

Report Ref No. CS/INC20011718/Gqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVAL 2X DOOR PANELS / PWR WINDOW MODULES.		180.00	60.00
			3,100.00	1,590.00
GRAND TOTAL			9,378.00	2,304.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,850.00

Report Ref No. CS/INC20011718/Gqf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.