

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20011721/QYF3E2

Date: 25/11/2020

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SHC4754X

Insured Vehicle No :

SJF384S

Date of Loss: 27/10/2020

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC4754X

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR1673589

Reg. Date: 01/04/2016 (Man. Year: 2015)

Chassis No: JTDKN36U805767751

Colour: Maroon

Odometer: 612808 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Fireza 6 mm

Rear Left Side:

Fireza 6 mm

Front Right Side: Fireza 6 mm

Rear Right Side:

Fireza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,402.80	120.00	3,282.80	96.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,436.00	400.00	1,036.00	72.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,838.80	520.00	4,318.80	89.25
Approved Total (Overridden) (S\$)		500.00		
Nett Amount (S\$)	4,838.80	500.00	4,338.80	89.67

INSPECTION

Date of Assignment: 28/10/2020

Date Inspected: 28/10/2020 Inspected At:

SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Nov 2020)

Parts: 144 TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC4754X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
2	10		*BUMPER CLIPS	Serviceable	21.00 F	*- F
3	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
4	1		*ARM SUB-ASSY, RR BUMPER RH	Serviceable	139.60 F	*- F
5	1		*ARM SUB-ASSY, RR BUMPER LH	Serviceable	139.60 F	*- F
6	1		*ANTENNA, ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
7	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
8	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
9	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
10	1		*BUMPER SEAL, RR LH	Serviceable	88.90 F	*- F
11	1		*BUMPER SEAL, RR RH	Serviceable	65.70 F	*- F
12	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
13	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
14	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
15	1		*UNDER COVER SUB-ASSY, RR FLOOR	Serviceable	514.50 F	*- F
16	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
17	1		*END PANEL	Serviceable	602.10 F	*- F
18	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
19	1		*BUMPER REAR	Repair	458.60 F	*- F
Total Parts (S\$)					3,402.80	120.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	738.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			1,436.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >