

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011725/GQF3E2

Date: 04/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800154060
<b>Claimant Vehicle No :</b> SGU3762X	<b>Insured Vehicle No :</b> SMG5745K
Date of Loss: 20/10/2020	Nature of Claim: TP Claim No: 7912492093SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGU3762X</b>		
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Engine No:	1AZE023709
Reg. Date:	14/05/2007 (Man. Year: 2006)	Chassis No:	MR053BK4107007146
Colour:	Black	Odometer:	281282 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	23/10/2020		
Date Inspected:	28/10/2020	Inspected At:	Lam Auto Pte Ltd 13 Defu Lane, #01-416 Singapore 539194
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Cut	0.00 F	*- F
4	1		*FRT BUMPER MOULDING	Scratched	0.00 F	*- F
5	1		*FRT RH HEADLAMP ASSY	Cut	0.00 F	*- F
6	1		*FRT RH FENDER	Buckled	0.00 F	*- F
7	1		*FRT RH FENDER INNER SHIELD	Deformed	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (\$\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**