

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011729/KTD3E2  
Date: 19/01/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00029462000  
Claimant Vehicle No : SDQ5151C Insured Vehicle No : GBA6992T  
Date of Loss: 25/10/2020 Nature of Claim: TP Claim No: SNM20D204069/C02/LOWCT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDQ5151C  
Make & Model: SUZUKI SWIFT, 1.6 (A) Engine No: M16A1326436  
Reg. Date: 25/01/2008 (Man. Year: 2007) Chassis No: JSAEJC31S00200938  
Colour: Metallic Yellow Odometer: 169538 km  
Engine Capacity: 1586 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16  
Front Left Side: Tourador 9 mm Rear Left Side: Tourador 9 mm  
Front Right Side: Tourador 9 mm Rear Right Side: Tourador 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,423.10	2,335.48	3,087.62	56.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	760.00	790.00	50.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,973.10</b>	<b>3,095.48</b>	<b>3,877.62</b>	<b>55.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,450.00</b>		
<b>(S\$)</b>	6,973.10	2,450.00	4,523.10	64.86
<b>+ GST 7.00/7.00% (S\$)</b>	488.12	171.50	316.62	64.87
<b>Nett Amount (S\$)</b>	<b>7,461.22</b>	<b>2,621.50</b>	<b>4,839.72</b>	<b>64.86</b>

### INSPECTION

Date of Assignment: 28/10/2020  
Date Inspected: 04/11/2020 Inspected At: Thiam Heng Huat Pte Ltd (SIN MING)  
176 SIN MING DRIVE, #05-14  
Singapore 575721  
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
<b>Parts:</b>	144	SUZUKI SWIFT 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDQ5151C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Dented	1,602.00 FL	*555.10 FL
2	2		*FRONT BUMPER SIDE RETAINER	Serviceable	130.00 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Serviceable	256.00 FL	*- FL
4	1		*SUPPORT PANEL	Repair	542.00 FL	*- FL
5	1		*FRONT GRILLE TOP BRACKET	Repair	39.00 FL	*- FL
6	1		*FRONT GRILLE TOP GARNISH	Serviceable	87.00 FL	*- FL
7	1		*FRONT GRILLE LOGO	Necessary	69.00 FL	*69.00 FL
8	1		*FRONT GRILLE	Cracked	391.85 FS	*250.00 FS
9	10		*FRONT BUMPER CLIP	Necessary	55.00 FS	*55.00 FS
10	1		*FRONT NUMBER PLATE WITH FRAME	Serviceable	55.00 FS	*- FS
11	2		*GRILLE LOGO CLIP	Not Necessary	11.00 FS	*- FS
12	8		*BONNET INSULATOR CLIPS	Not Necessary	44.00 FS	*- FS
13	1		*CARBON FIBRE BONNET	Cracked	2,500.00 FS	*1,500.00 FS
14	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,831.85</b>	<b>2,429.10</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	408.75	93.62
<b>Total Parts (\$\$)</b>	<b>5,423.10</b>	<b>2,335.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	800.00	350.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	10.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	600.00	400.00
4	TO RUST PROOF ALL AFFECTED PORTION AFTER REPAIR	New	100.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,550.00</b>	<b>760.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >