

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC20011730/KTF3E2

Date: 30/11/2020

REFERENCE

Insured/Claimant: H P CONSTRUCTION & ENGINEERING PTE LTD	Policy No: Z/20/VC06/107022	
Date of Loss: 26/10/2020	Nature of Claim: OD	Claim No: 20/20/20/VC06/023825

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP1980J		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C05638
Reg. Date:	08/04/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20365
Colour:	White	Odometer:	243489 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$47,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 8/8 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,548.50	11,932.75	9,615.75	44.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,780.00	2,530.00	5,250.00	67.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,328.50	14,462.75	14,865.75	50.69
Approved Total (Overridden) (S\$)		11,550.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	29,328.50	10,950.00	18,378.50	62.66
+ GST 7.00/7.00% (S\$)	2,053.00	766.50	1,286.50	62.66
Nett Amount (S\$)	31,381.50	11,716.50	19,665.00	62.66

INSPECTION

Date of Assignment:	28/10/2020 Present Location:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
Date Inspected:	28/10/2020 Inspected At:	Falcon-Air Auto Services Pte Ltd (Sin Ming)
		176 Sin Ming Drive #01-06, Sin Ming

Autocare
Singapore 575721

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Nov 2020)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21ER4SDEB (CBU) (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1980J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Windscreen Glass Rubber (WCP)	Necessary	250.00 F	*250.00 F
2	1		*Front Wiper Garnish (WCP)	Cracked	390.00 F	*390.00 F
3	10		*Front Wiper Garnish Clip	Necessary	40.00 FS	*40.00 FS
4	1		*Front Wing Mirror Garnish (WCP)	N/S Cracked	620.00 F	*310.00 F
5	1		*LH Front Wing Mirror (Small) (WCP)	Missing	52.00 F	*52.00 F
6	1		*Front Panel (WCP)	Bent	1,350.00 F	*1,350.00 F
7	1		*Front Panel Emblem (FUSO) (WCP)	Necessary	105.00 F	*105.00 F
8	1		*Front Panel Body Sealant	Not Necessary	80.00 FS	*- FS
9	1		*Radiator Grille (WCP)	Broken	750.00 F	*750.00 F
10	1		*Radiator Grille Logo (WCP)	Necessary	68.00 F	*68.00 F
11	10		*Radiator Grille Clip	Necessary	40.00 FS	*40.00 FS
12	2		*Headlamp (WCP)	Mtg Cracked	840.00 F	*840.00 F
13	1		*Front Side Lamp (WCP)	N/S Broken	400.00 F	*200.00 F
14	1		*Front Signal Lamp (WCP)	N/S Broken	560.00 F	*280.00 F
15	1		*Front Bumper (WCP)	Bent	750.00 F	*750.00 F
16	1		*Front Bumper Bracket (WCP)	O/S Bent	330.00 F	*165.00 F
17	1		*Front Bumper Side Garnish (WCP)	N/S Dented / Cut	580.00 F	*290.00 F
18	1		*Front Number Plate	Bent	45.00 FS	*25.00 FS
19	1		*Front Cabin Crossmember (WCP)	Bent	750.00 F	*750.00 F
20	2		*Front Cabin Crossmember Bush (WCP)	Necessary	360.00 F	*360.00 F
21	1		*Dashboard (WCP)	Serviceable	1,900.00 F	*- F
22	1		*LH Front Dashboard Lower Cover (WCP)	Serviceable	530.00 F	*- F
23	1		*Air Con Condenser Assembly (small) w/fan (WCP)	Serviceable	1,050.00 F	*- F
24	1		*Air Con Evaporator Unit (WCP)	Housing Cracked	2,500.00 F	*2,500.00 F
25	1		*Air Con Blower Unit (WCP)	Serviceable	2,450.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*Air Con Suction Hose (WCP)	Dented	380.00 F	*380.00 F
27	1		*Air Con Discharge Hose (WCP)	Dented	370.00 F	*370.00 F
28	1		*Air Con Liquid Pipe (WCP)	Serviceable	380.00 F	*- F
29	1		*Brake Pipe (WCP)	Serviceable	525.00 F	*- F
30	2		*Brake Fluid	Not Necessary	80.00 FS	*- FS
31	1		*Horn (WCP)	Dented (1Pc Only)	250.00 F	*125.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	18,775.00	10,390.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	2,773.50	1,542.75
Total Parts (\$\$)	21,548.50	11,932.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To focus headlamp }	New	50.00	20.00
2	To check wiring {	New	50.00	0.00
3	To remove/refix front windscreen	New	120.00	80.00
4	To remove/refix dashboard to facilitate repairs	New	480.00	250.00
5	To remove/refix air con condenser, pipe, etc, to vacuum and top up air con gas	New	150.00	100.00
6	To remove/replace evaporator and blower unit	New	400.00	150.00
7	To remove/refix inner trims, seats, garnish, etc to facilitate repairs	New	350.00	0.00
8	To replace brake pipe and to bleed air	New	300.00	30.00
9	To crane cabin to facilitate repairs and to fix back	New	800.00	0.00
10	To straighten chassis frame	New	600.00	0.00
11	To scan and clear fault code	New	280.00	0.00
12	To remove necessary parts to cut-out outer panel, repair inner panel, re-weld outer panel and replacement of parts	New	2,400.00	1,000.00
13	To putty and spray paint on accident damage area	New	1,800.00	900.00
Gross Labour Cost (\$\$)			7,780.00	2,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >