

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011739/R1VF3Q2

Date: 25/11/2020

REFERENCE

| | | | | |
|-------------------|-----------------|------------------|------------|------------------------|
| Insured/Claimant: | CHIN LEONG YONG | Policy No: | 2100467555 | |
| Date of Loss: | 28/10/2020 | Nature of Claim: | OD | Claim No: 0538307605SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SDK6168E | | |
| Make & Model: | KIA FORTE K3, 1.6 SX (A) | Engine No: | G4FGFH608138 |
| Reg. Date: | 27/05/2016 (Man. Year: 2015) | Chassis No: | KNAFZ411MG5570090 |
| Colour: | Blue | Odometer: | 49551 km |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | S\$53,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 215/45ZR17 | Rear Tyre Size: | 215/45ZR17 |
| Front Left Side: | Roadstone 6 mm | Rear Left Side: | Roadstone 6 mm |
| Front Right Side: | Roadstone 6 mm | Rear Right Side: | Roadstone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 7,766.80 | 6,247.20 | 1,519.60 | 19.57 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,350.00 | 5,745.00 | 1,605.00 | 21.84 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 15,116.80 | 11,992.20 | 3,124.60 | 20.67 |
| - Excess (S\$) | 300.00 | 300.00 | 0.00 | 0.00 |
| (S\$) | 14,816.80 | 11,692.20 | 3,124.60 | 21.09 |
| + GST 7.00/7.00% (S\$) | 1,037.18 | 818.45 | 218.73 | 21.09 |
| Nett Amount (S\$) | 15,853.98 | 12,510.65 | 3,343.33 | 21.09 |

INSPECTION

Date of Assignment: 28/10/2020

Date Inspected: 28/10/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|-------------|-------------|--------------|
| 1 | 1 | | *LAMP ASSY-REAR COMBINATION,RH | Cracked | 843.00 FL | *843.00 FL |
| 2 | 1 | | *WHEEL ASSY-ALUMINIUM | Scratched | 958.00 FL | *958.00 FL |
| 3 | 1 | | *PANEL ASSY-QUARTER OUTER,RH | Buckled | 1,213.00 FL | *1,213.00 FL |
| 4 | 1 | | *PANEL ASSY-RR COMB LAMP HSG,RH | Serviceable | 123.00 FL | *- FL |
| 5 | 1 | | *PANEL ASSY-REAR DOOR RH | Buckled | 1,361.00 FL | *1,361.00 FL |
| 6 | 1 | | *PANEL ASSY-FRONT DOOR RH | Buckled | 1,542.00 FL | *1,542.00 FL |
| 7 | 1 | | *FILM-ANTI CHIPPG RH | Necessary | 27.00 FL | *27.00 FL |
| 8 | 1 | | *HANDLE ASSY-DOOR OUTSIDE | Scratched | 214.00 FL | *214.00 FL |
| 9 | 1 | | *BASE ASSY-FR DR O/S HANDLE,RH | Serviceable | 52.00 FL | *- FL |
| 10 | 1 | | *LATCH ASSY-FRONT DOOR,RH | Serviceable | 253.00 FL | *- FL |
| 11 | 1 | | *W/STRIP-RR DR BODY SIDE RH | Serviceable | 103.00 FL | *- FL |
| 12 | 1 | | *W/STRIP-ASSY RR DR SIDE RH | Serviceable | 114.00 FL | *- FL |
| 13 | 1 | | *W/STRIP-FR DR BODY SIDE RH | Serviceable | 94.00 FL | *- FL |
| 14 | 1 | | *W/STRIP ASSY-FR DR SIDE RH | Serviceable | 122.00 FL | *- FL |
| 15 | 1 | | *W/STRIP ASSY-FR DR BELT O/S RH | Serviceable | 58.00 FL | *- FL |
| 16 | 1 | | *W/STRIP ASSY-RR DR BELT O/S RH | Serviceable | 89.00 FL | *- FL |
| 17 | 1 | | *GUARD ASSY-REAR WHEEL RH | Serviceable | 75.00 FL | *- FL |
| 18 | 1 | | *GLASS ASSY-REAR WINDOW | Serviceable | 534.00 FL | *- FL |
| 19 | 1 | | *MOULDING-REAR WINDOW GLASS | Necessary | 27.00 FL | *27.00 FL |
| 20 | 2 | | *STOPPER-RR WINDOW GLASS | Necessary | 8.00 FL | *8.00 FL |
| 21 | 8 | | *PAD-WINDSHIELD GLASS | Necessary | 16.00 FL | *16.00 FL |
| 22 | 1 | | *BLACK TAPE-FR DR FRAME UPR,RH | Necessary | 13.00 FL | *13.00 FL |
| 23 | 1 | | *BLACK TAPE-RR DR FRAME UPR,RH | Necessary | 11.00 FL | *11.00 FL |
| 24 | 1 | | *TAPE-RR DR FRAME BLACK RR,RH | Necessary | 8.00 FL | *8.00 FL |
| 25 | 1 | | *BLACK TAPE-FR DR RR,RH | Necessary | 12.00 FL | *12.00 FL |
| 26 | 1 | | *COVER-RR BUMPER | Scratched | 791.00 FL | *791.00 FL |
| 27 | 1 | | *COVER-RR BUMPER,UPR | Serviceable | 245.00 FL | *- FL |
| 28 | 1 | | *BRACKET-RR BUMPER SIDE MTG,RH | Cracked | 33.00 FL | *33.00 FL |
| 29 | 1 | | *MIRROR ASSY-OUTSIDE RR VIEW,RH | Cracked | 685.00 FL | *685.00 FL |
| 30 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 31 | 1 | | *COVER-FR DR O/S HDL,DRIVER | Scratched | 22.00 FL | *22.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 9,696.00 | 7,804.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,929.20 | 1,556.80 |
| Total Parts (\$\$) | 7,766.80 | 6,247.20 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

| No | Qty | Particulars | Repairer's | Amount |
|----------------------------|-----|-----------------------|-------------|-------------|
| Miscellaneous Items | | | | |
| 1 | 1 | *OD/TP Case (Insurer) | - | 0.00 |
| Sub Total (\$\$) | | | 0.00 | 0.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER,REAR RH FENDER,REAR RH DOOR,FRT RH DOOR & AFFECTED AREA.TO REPAIR ON FRT RH FENDER & RH B-PILLAR | New | 2,800.00 | 2,000.00 |
| 2 | PAINT WORK ON REAR BUMPER,REAR RH FENDER,REAR RH DOOR,FRT RH DOOR,FRT RH FENDER,RH B-PILLAR & RH WING MIRROR COVER | New | 2,450.00 | 1,925.00 |
| 3 | TO REMOVE & INSTALL REAR PARKING ASSIST | New | 120.00 | 100.00 |
| 4 | TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL | New | 120.00 | 120.00 |
| 5 | TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL | New | 120.00 | 0.00 |
| 6 | TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR | New | 120.00 | 120.00 |
| 7 | TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR | New | 120.00 | 120.00 |
| 8 | REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR | New | 240.00 | 240.00 |
| 9 | TO APPLY WINDSCREEN SEALANT | New | 80.00 | 80.00 |
| 10 | TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT | New | 120.00 | 120.00 |
| 11 | TO TRANSFER REAR RH RIM INCLUDING BALANCING | New | 50.00 | 30.00 |
| 12 | TO APPLY SEALANT ON AFFECTED AREA | New | 120.00 | 40.00 |
| 13 | PERFORM RUST PREVENTION | New | 120.00 | 80.00 |
| 14 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 15 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| 16 | REPAIR RH CENTRE DOOR PILLAR | New | 200.00 | 200.00 |
| 17 | SPRAY PAINT RH CENTRE DOOR PILLAR | New | 420.00 | 420.00 |
| Gross Labour Cost (\$\$) | | | 7,350.00 | 5,745.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >