

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2007719

INV Date 17/11/2020

Reference CC3/EQI20011740/Ksd3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 613R

Insured Veh. GBD 6349K

Claim No. DM20HO01617/JT

Policy No.

Accident Date 23/10/2020

Inspection Date 27/10/2020

Description	Total
Survey Inspection	230.00
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ II	NSURANCE COM	PANY LTD	Ref : CC3/EQI200117	40/Ksd3e2
#17-0	XWELL ROAD 00 TOWER BLOC COMPLEXSING		Date: 17-11-2020	
			Code: EQI	
1.			:- THIRD PARTY CLAIN	
	Insured Veh.	GBD 6349K	Veh. Inspected	SHD 613R
	Policy No.		Coverage (\$)	0.00
	Claim No.	DM20HO01617/JT	Excess (\$)	0.00
	Assign From		Assign Date	27/10/2020
2.		Vehicle Partic	culars & Condition	
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VF1ABL15AUC283403	Colour	METALLIC WHITE / RED
	Odometer	407927	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	SAILUN	8 mm
	L/H Front Tyre	215/60 R16	SAILUN	8 mm
	R/H Rear Tyre	215/60 R16	SAILUN	7 mm
	L/H Rear Tyre	215/60 R16	SAILUN	7 mm
4.		Description	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		General	Information	
	Accident Date	23/10/2020	Inspection Date	27/10/2020
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.		Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	2 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 613R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED / WARPED	561.70	561.70
1	BUMPER LOWER REAR	SERVICEABLE	411.90	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	547.80	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	TAILLAMP LH	CUT	401.40	401.40
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	1,933.20	-
1	WHEELARCH REAR LH	SERVICEABLE	275.40	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
	LESS 10% DISCOUNT		-515.05	-96.31
			4,635.40	866.79
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	75.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	60.00	-
1	SET BUMPER BRACKET SIDE CLIP RR (SN)	NOT NECESSARY	70.00	-
1	SET BUMPER RETAINER CLIP RR (SN)	NOT NECESSARY	65.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	70.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	75.00	-
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	50.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	EXHAUST MOUNTING (SN)	NOT NECESSARY	65.00	-
1	FENDER SCREW (SN)	NOT NECESSARY	60.00	-
1	FENDER NUT (SN)	NOT NECESSARY	60.00	-
			1,530.00	66.00

Report Ref No. CC3/EQI20011740/Ksd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR AND FENDER PANEL REAR LH.		1,600.00	400.00
	TO REMOVE AND REFIT REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	250.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	440.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,560.00	920.00
	GRAND TOTAL		10,725.40	1,852.79

RECOMMENDED COST OF LUMP SUM REPAIRS
(TO ITS PRE-ACCIDENT CONDITION)

1,500.00

Report Ref No. CC3/EQI20011740/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy licklifts. repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT	
Date Of Report	26/10/2020 09:37	
Date Of Accident	23/10/2020 18:00	,
Exact Location Of Accident	BLK 703 BEDOK RESERVOIR ROAD CARPARK	
Country/State of Loss	SINGAPORE	8 Y 1 T 1 S
Country/State of Loss	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD613R	
		al water
Insured/Policyholder	TRANS-CAB SERVICES PTE LTD	
Name Of Registered Owner	2XXXX878K	
Co Reg No	CLAIMS@TRANSCAB.COM.SG	
Email Address		
Mobile Phone No	OFFICE-62866666	******
Alternative Phone No		
Vehicle Particulars	RENAULT	
Manufacturer	LATITUDE-2.0 L (A)	
Model		
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD	
Are you claiming under your own insurance policy for repair to your vehicle?	NO	
If No, Please state action to be taken	THIRD PARTY	
Vehicle Category	TAXI	
Insurance Company		
Name of Insurance Company	AXA INSURANCE PTE LTD	
Type Of Coverage	THIRD PARTY	
Fleet Policy	YES	
Policy Number	VFX/P2348706	
Cover Note Number		X (5.55)
Driver		2.00
Name of Driver	KHOO CHEE KONG	
NRIC No	SXXXX362F	
Date Of Birth	15/09/1965	
Occupation	OUTDOOR	
Date Of Driving Pass	12/07/1984	
Driving Experience	36 YEARS AND 3 MONTHS	
Gender	MALE	
Mobile Number	(LOCAL) +65-97900736	
Fax Number		
Contact Number		
	NOEMAIL	

Address

BLK 708 HOUGANG AVENUE 2

#07-61

Postcode

530708

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

On 23.10.2020 at about 1800hours, I was reversing my taxi along Blk 703 Bedok Reservoir Road carpark to park my taxi when I check my rear and making a reversing. Suddenly I felt an impact. Vehicle B (GBD6349K) making a reverse without checking his rear and hit onto my taxi's left side rear portion

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD6349K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

GOODS VEHICLE

Name of Driver

DENISE NG

NRIC/Passport Number

Contact Number

98739871

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1






51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 613R

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



