



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM20011741/Gbs3q2 Date: 05/02/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJK 6574U	Veh. Inspected	SMQ 757G	
Policy No.	GA508055	Coverage (\$)	0.00	
Claim No.	S0M02VZV	Excess (\$)	0.00	
Assign From		Assign Date	28/10/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FIT 1.3	c.c	0	
Engine No.	HIDDEN	Year of Reg.	0.00	
Chassis No.	GK31351139	Colour	GREY	
Odometer	22022 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	DUNLOP	6 mm	
L/H Front Tyre	175/70 R14	DUNLOP	6 mm	
R/H Rear Tyre	175/70 R14	DUNLOP	6 mm	
L/H Rear Tyre	175/70 R14	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	24/10/2020	Inspection Date	28/10/2020	
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KKAI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	