

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS20011742/KTF3E2

Date: 17/11/2020

REFERENCE

Insured/Claimant:	CHEW STEPHEN	Policy No:	MPC20P00148300	
Date of Loss:	26/10/2020	Nature of Claim:	OD	Claim No: DMPC2000182H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBZ190Z		
Make & Model:	MERCEDES-BENZ E200, 1.8 CGI BlueEfficiency (W212) (A)	Engine No:	27186030636148
Reg. Date:	11/04/2013 (Man. Year: 2013)	Chassis No:	WDD2120482A758007
Colour:	Metallic Grey	Odometer:	70296 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,259.70	4,177.70	82.00	1.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	870.00	50.00	5.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,179.70	5,047.70	132.00	2.55
Approved Total (Overridden) (S\$)		4,000.00		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	5,179.70	3,500.00	1,679.70	32.43
+ GST 7.00/7.00% (S\$)	362.58	245.00	117.58	32.43
Nett Amount (S\$)	5,542.28	3,745.00	1,797.28	32.43

INSPECTION

Date of Assignment: 28/10/2020 Present Location:
Date Inspected: 29/10/2020 Inspected At:

Alan's United Auto Pte Ltd (HQ)
Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)
Parts:	143	MERCEDES-BENZ E200 1.8 CGI BlueEfficiency (W212) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBZ190Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA (WCP)	Cracked	1,200.00 F	*1,200.00 F
2	2		*FRONT BUMPER PARKING SENSOR (WCP)	Cracked	290.00 F	*290.00 F
3	1		*FRONT RH PARKING SENSOR (WCP)	Cracked	145.00 F	*145.00 F
4	3		*FRONT PARKING SENSOR O RING (WCP)	Necessary	12.00 F	*12.00 F
5	1		*FRONT BUMPER SPONGE (CENTRE) (WCP)	Serviceable	70.00 F	*- F
6	1		*FRONT BUMPER LOWER GRILLE (WCP)	Distorted	95.00 F	*95.00 F
7	1		*FRONT BUMPER NO.PLATE GARNISH (WCP)	Dented	80.00 F	*80.00 F
8	1		*RADIATOR GRILLE (WCP)	Cracked	580.00 F	*580.00 F
9	1		*RADIATOR GRILLE LOGO (WCP)	Necessary	33.00 F	*33.00 F
10	1		*RADIATOR GRILLE CENTRE BRACKET (WCP)	Cracked	18.00 F	*18.00 F
11	1		*RADIATOR GRILLE TOP COVER (WCP)	Cracked	86.00 F	*86.00 F
12	1		*BRACE PANEL (WCP)	Bent	32.00 F	*32.00 F
13	1		*CONDENSER GUIDE COVER (WCP)	Cracked	55.00 F	*55.00 F
14	1		*CONDENSER GUIDE LOWER (WCP)	Cracked	95.00 F	*95.00 F
15	2		*BONNET SPRING STOPPER (WCP)	Cracked	36.00 F	*36.00 F
16	2		*HEADLAMP (WCP)	Mtg Cracked	1,000.00 F	*1,000.00 F
17	1		*FRONT NO.PLATE WITH BOX	Dented	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,877.00	3,802.00
+ Margin on L,N Items 10.00/10.00% (S\$)	382.70	375.70
Total Parts (S\$)	4,259.70	4,177.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM.	New	20.00	20.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	400.00	400.00
3	TO REMOVE DAMAGED PARTS,PANEL BEATING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	500.00	450.00
Gross Labour Cost (S\$)			920.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >