

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011744/AQF3E2

Date: 18/03/2021

REFERENCE

Insured/Claimant: CHAO LYNNE MAREE @ BEASLEY LYNNE MAREE Policy No: 1800142787-01

Date of Loss: 22/10/2020

Nature of Claim: OD

Claim No: 4973285847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2416E	Engine No:	CVK073152
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Chassis No:	WAUZZZF55KA009601
Reg. Date:	11/12/2018 (Man. Year: 2018)	Odometer:	15994 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$148,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,814.00	1,196.00	7,618.00	86.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,372.00	1,402.00	4,970.00	78.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,186.00	2,598.00	12,588.00	82.89
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,586.00	1,998.00	12,588.00	86.30
+ GST 7.00/7.00% (S\$)	1,021.02	139.86	881.16	86.30
Nett Amount (S\$)	15,607.02	2,137.86	13,469.16	86.30

INSPECTION

Date of Assignment: 28/10/2020

Date Inspected: 28/10/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Repair	3,091.00 FS	*- FS
2	1		*FRONT DOOR OUTER SEAL	Not Necessary	220.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
5	1		*FRONT DOOR CATCH	Not Necessary	119.00 FS	*- FS
6	1		*DOOR HANDLE TRIM PLATE	Not Necessary	87.00 FS	*- FS
7	1		*DOOR HANDLE TRIM - RH	Not Necessary	135.00 FS	*- FS
8	1		*EXTERIOR MIRROR MOUNTING - RH	Cut	1,077.00 FS	*861.60 FS
9	1		*MIRROR CAP - RH	Missing	261.00 FS	*208.80 FS
10	1		*MIRROR GLASS - RH	Not Necessary	1,649.00 FS	*- FS
11	1		*ROOF MOULDING - RH	Not Necessary	622.00 FS	*- FS
12	1		*WINDOW SLOT SEAL - RH	Not Necessary	394.00 FS	*- FS
13	1		*CORNER TRIM - RH	Not Necessary	45.00 FS	*- FS
14	1		*FRONT DOOR WINDOW - RH	Not Necessary	286.00 FS	*- FS
15	1		*DOOR TRIM - RH	Necessary	157.00 FS	*125.60 FS
16	1		*FENDER TRIM - RH	Not Necessary	157.00 FS	*- FS
17	1		*TYRE PRESSURE DATA PLATE	Not Necessary	36.00 FS	*- FS
18	1		*WATER DEFLECTOR STRIP	Not Necessary	66.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,814.00 1,196.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	New	280.00	0.00
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO FACILITATE RENEWAL OF RHS FRONT DOOR WINDOW GLASS AND RHS WING MIRROR ASSY.	New	400.00	260.00
3	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS.	New	400.00	0.00
4	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS UPPER A-PILLAR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,600.00	250.00
5	TO RESPRAY RHS FRONT DOOR, RHS FRONT FENDER, RHS UPPER A-PILLAR, DOOR HANDLE AND RHS WING MIRROR COVER.	New	3,500.00	700.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			6,372.00	1,402.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >