



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103849

INV Date 02/06/2021

Reference CC4/LPC20011750/Aga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 6702C

Insured Veh. GBG 8621U

Claim No. 19/20/20/VC00/023826

Policy No.

Accident Date 28/10/2020

Inspection Date 29/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20011750/Aga3q2 Date: 02/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 8621U		Veh. Inspected	SLN 6702C
Policy No.			Coverage (\$)	0.00
Claim No.	19/20/20/VC00/023826		Excess (\$)	0.00
Assign From	KENNY		Assign Date	28/10/2020
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET ORLANDO		c.c	1362
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	KL1YA7589HK615353		Colour	WHITE
Odometer	90391 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	245/45 R18		CONTINENTAL	6 mm
L/H Front Tyre	245/45 R18		CONTINENTAL	6 mm
R/H Rear Tyre	245/45 R18		CONTINENTAL	6 mm
L/H Rear Tyre	245/45 R18		CONTINENTAL	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2020		Inspection Date	29/10/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6702C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,355.90	1,355.90
1	REAR BUMPER TOP	CRACKED	230.00	166.00
1	REAR BUMPER CENTRE	DEFORMED	850.00	493.00
1	REAR BUMPER LOWER	CUT	422.00	223.00
2	REAR BUMPER SIDE RETAINER @\$62.40	NECESSARY	124.80	124.80
2	REAR BUMPER REFLECTOR @\$80.00	NOT NECESSARY	160.00	-
1	REAR BUMPER CENTRE WHITE & RED LIGHT	CRACKED	380.00	380.00
4	REAR BUMPER REVERSE SENSOR @\$320.00	DAMAGED (2 PCS ONLY)	1,280.00	400.00
1	REAR BUMPER BEAM	CRACKED	211.90	148.00
	LESS 10% DISCOUNT		-501.46	-329.07
			4,513.14	2,961.63
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
			20.00	20.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.		1,000.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	200.00
	WIRING CHECK .		80.00	30.00
	TO REMOVE AND REFIX REAR REVERSE SENSOR SETTING.		100.00	50.00
			2,180.00	480.00
GRAND TOTAL			6,713.14	3,461.63
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CC4/LPC20011750/Aga3q2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser****DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 6702C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 6702C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

