

FBP 5057S

To wing — \$35 —

To wing to idac — \$35 —

Front Mudguard — \$70 cut —

Fork alignment — 280. 120 Labour
under Bracket — \$195. x Xnn

Front Spoling^{rim} — \$245 del —

Front Brake disc — \$135 bt —

Front Central Cover \$125 cut — ^{mm} ✓

R/L Front Signal — \$96. ^{mm} ✓

Front No plate — \$25. bt —

R/L Front Side Failing — \$170. cut —

Front Head light \$98. ^{mm} ✓

Head Cowling — \$85. ^{mm} ✓

Head Cowling ^{windscreen} wiskin — \$38. ^{mm} ✓
Xnn

Headle Bar 1pc — \$98. ? 合國摩托私人有限公司
KIM KOCK MOTOR FTE LTD

Headle Grip R/L \$60. ^{mm} ✓
Dk 27A, Jurong Port Road, #01-10,
Singapore 619101
Tel: 0235 0226 Fax: 0235 2010

MIRPLE R/L — \$50. cut ✓

Meter Assy — \$295.00 ✓

Brake Pump Assy — \$145.00 ✓
given inside

Body Central Big Coker — \$165.00 ✓

Front Foot Rest BAR Assy — \$78.00 ✓

AJER PIPE Assy — \$295.00 ✓

(R) Rear Side Failing — \$125.00 ✓

(L) Rear Foot Rest BAR — \$78.00 ✓

(L) Rear Foot Rest — \$38.00 ✓

E33 - Rear Civi Box — \$165.00 ✓

2623 Rear Civi Box Brakf — \$135.00 ✓
10% 2360.70

390 Rear No Plate — \$28.00 ✓

2750.70 Labuar — \$280.00 ✓

Tan Kah 97445745
in 29/10/2002 4:15pm

\$3791

Lumpsum

Resurvey after repair

for the labour

金國摩哆私人有限公司

KIM KOCK MOTOR PTE LTD

Blk 27A, Jurong Port Road, #01-19,

Singapore 619101

Tel: 6265 0226 Fax: 6265 2593

1/s \$2200

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company