

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 5857S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT MUDGUARD	CUT	78.00	78.00
1	UNDER BRACKET	NOT NECESSARY	195.00	-
1	FRONT SPOLING RIM	DENTED	245.00	245.00
1	FRONT BRAKE DISC	BENT	135.00	135.00
1	FRONT CENTRAL COVER	CUT	125.00	125.00
2	R/L FRONT SIGNAL	CRACKED	96.00	96.00
1	FRONT NO PLATE	BENT	25.00	25.00
2	R/L FRONT SIDE FAILING	CUT	170.00	170.00
1	FRONT HEAD LIGHT	CRACKED	98.00	98.00
1	HEAD COWLING	CRACKED	85.00	85.00
1	HEAD COWLING WISKIM	CRACKED	38.00	38.00
1	HANDLE BAR	NOT NECESSARY	98.00	-
2	HANDLE GRIP R/L	DENTED	68.00	68.00
2	MIRRLE R/L	CUT	58.00	58.00
1	METER ASSY	CRACKED	295.00	295.00
1	BRAKE PUMP ASSY	NOT NECESSARY	145.00	-
1	BODY CENTRAL BIG COVER	CRACKED	165.00	165.00
1	FRONT FOOT LEST BAR ASSY	BENT	78.00	78.00
1	AJER PIPE ASSY	DENTED	295.00	295.00
1	(R) REAR SIDE FAILING	CRACKED	125.00	125.00
1	(L) REAR FOOT LEST BAR	BROKEN	78.00	78.00
1	(L) REAR FOOT LEST	MISSING	38.00	38.00
1	E33 REAR CIVI BOX	CUT	165.00	165.00
1	REAR CIVI BOX BRACKET	BENT	135.00	135.00
1	REAR NO PLATE	BENT	28.00	28.00
	LESS 10% DISCOUNT		-	-262.30
			3,061.00	2,360.70
	<u>LABOUR</u>			
	TOWING.		35.00	35.00
	TOWING TO IDAC.		35.00	35.00

Report Ref No. CS/SMO20011753/T1Kvd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	FORK ALIGNMENT.		380.00	120.00
	LABOUR.		280.00	200.00
			730.00	390.00
	GRAND TOTAL		3,791.00	2,750.70

RECOMMENDED COST OF LUMP SUM REPAIRS		2,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO20011753/T1Kvd3e2

KONG SENG CHEONG

Licensed Appraiser