

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20011755/GTF3E2  
**Date:** 10/11/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700088703
<b>Claimant Vehicle No :</b> FX8840S	<b>Insured Vehicle No :</b>	SLW8929E
Date of Loss: 28/10/2020	Nature of Claim:	TP Claim No: 5091000989SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>FX8840S</b>	Engine No:	G3P3E0001318
Make & Model:	YAMAHA JUPITER T150, 150cc	Chassis No:	MH3UG131000001330
Reg. Date:	21/02/2020 (Man. Year: 2020)	Odometer:	25022 km
Colour:	Green		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	60/80-17	Rear Tyre Size:	70/80-17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	28/10/2020	Inspected At:	JC Motor Consultancy (HQ)
Date Inspected:	29/10/2020		464 Macpherson Road
			Singapore 368182
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
3	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
6	1		*BRAKE RESERVOIR	Cut	0.00 F	*- F
7	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
8	1		*SIDE FAIRING	Cut	0.00 F	*- F
9	1		*FAIRING SHIELD	Cut	0.00 F	*- F
10	1		*FOOT BRAKE	Cut	0.00 F	*- F
11	1		*FRONT FOOT REST	Cut	0.00 F	*- F
12	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
13	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
14	1		*REAR RH SIGNAL LAMP	Cut	0.00 F	*- F

F=Franchise part.

**Total Parts (\$)**      **0.00**      **0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**