

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20011756/RPA3Q2**Date:** 14/12/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900259957
<b>Claimant Vehicle No :</b>	FBM652B	<b>Insured Vehicle No :</b>	SMJ1839J
Date of Loss:	21/10/2020	Nature of Claim:	TP
		Claim No:	9771193125SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>FBM652B</b>	Engine No:	G3E6E0235981
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740G0039061
Reg. Date:	29/06/2017 (Man. Year: 2016)	Odometer:	74522 km
Colour:	Multi-colour		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	80/90-17	Rear Tyre Size:	110/70-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,262.00	1,065.50	196.50	15.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	865.00	550.00	315.00	36.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,127.00</b>	<b>1,615.50</b>	<b>511.50</b>	<b>24.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,127.00	1,300.00	827.00	38.88
<b>+ GST 7.00/7.00% (S\$)</b>	148.89	91.00	57.89	38.88
<b>Nett Amount (S\$)</b>	<b>2,275.89</b>	<b>1,391.00</b>	<b>884.89</b>	<b>38.88</b>
<b>+ Loss of Use (5.0 x S\$15.00/day) (S\$)</b>		75.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,473.45</b>		

**INSPECTION**

Date of Assignment:	28/10/2020	Hua Chin (2000) Trading Motor Service Centre (HQ)
Date Inspected:	29/10/2020 Inspected At:	50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING
Estimated Period of Repair:	4.0 days	Singapore 659578

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR	Scratched	60.00 FL	*60.00 FL
2	1		*BRAKE LEVER	Scratched	40.00 FL	*40.00 FL
3	1		*CLUTCH LEVER	Not Necessary	40.00 FL	*- FL
4	1		*BALANCER	Scratched	45.00 FL	*45.00 FL
5	1		*SET COVER	Cut	550.00 FL	*550.00 FL
6	1		*PIPE PROTECTOR	Scratched	75.00 FL	*75.00 FL
7	1		*BOX	Scratched	180.00 FS	*150.00 FS
8	1		*INSIDE COWLING	Scratched	60.00 FL	*60.00 FL
9	1		*HANDLE BAR	Not Necessary	85.00 FL	*- FL
10	1		*FOOTREST	Scratched	75.00 FL	*75.00 FL
11	1		*BRAKE PEDAL	Scratched	60.00 FL	*60.00 FL
12	1		*HANDLE GRID	Scratched	30.00 FL	*30.00 FL
13	1		*MUDGUARD	Repair	60.00 FL	*- FL
14	1		*NO PLATE (REAR)	Bent	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,380.00	1,165.00
- List Item Discount on L Items 10.00/10.00% (\$)	118.00	99.50
Total Parts (\$)	1,262.00	1,065.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RIM	New	405.00	200.00
2	TOWING	New	60.00	0.00
3	LABOUR CHARGE	New	400.00	350.00
<b>Gross Labour Cost (S\$)</b>			<b>865.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >