

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 8198Z

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER (CONSISTENT) | DEFORMED | 575.70 | 575.70 |
| 1 | FRONT BUMPER LOWER GRILLE (CONSISTENT) | CRACKED | 107.70 | 107.70 |
| 1 | FRONT BUMPER UPPER GRILLE C/W LOGO (CONSISTENT) | CRACKED | 167.90 | 167.90 |
| 2 | FRONT BUMPER FOG LAMP @\$189.40 (CONSISTENT) | NOT NECESSARY | 378.80 | - |
| 1 | FRONT BUMPER LOWER BEAM (CONSISTENT) | NOT NECESSARY | 147.10 | - |
| 1 | FRONT BUMPER NUMBER PLATE HOLDER (CONSISTENT) | BENT | 87.90 | 87.90 |
| 2 | FRONT BUMPER TOWING HOOD @\$19.20 (CONSISTENT) | NOT NECESSARY | 38.40 | - |
| 2 | FRONT BUMPER SIDE RETAINER @\$34.20 (CONSISTENT) | NECESSARY | 68.40 | 68.40 |
| 1 | FRONT BUMPER REINFORCEMENT (CONSISTENT) | NOT NECESSARY | 410.50 | - |
| 1 | FRONT BUMPER REINFORCEMENT SPONGE (CONSISTENT) | CRACKED | 110.70 | 110.70 |
| 1 | FRONT BUMPER ENGINE UNDER COVER (CONSISTENT) | NOT NECESSARY | 127.40 | - |
| 2 | HEADLAMP (LED) @\$2234.60 (CONSISTENT) | O/S CRACKED | 4,469.20 | 2,234.60 |
| 2 | HEADLAMP LOWER BRACKET @\$39.10 (CONSISTENT) | NOT NECESSARY | 78.20 | - |
| 2 | FRONT FENDER COWLING @\$106.60 (CONSISTENT) | NOT NECESSARY | 213.20 | - |
| 1 | FRONT SUPPORT TOP PANEL (CONSISTENT) | NOT NECESSARY | 217.40 | - |
| 2 | HORN @\$78.30 (CONSISTENT) | NOT NECESSARY | 156.60 | - |
| 1 | AIRCON CONDENSOR AND GUARD (CONSISTENT) | NOT NECESSARY | 28.40 | - |
| 1 | REAR BUMPER (CONSISTENT) | DEFORMED | 537.70 | 537.70 |
| 5 | REAR BUMPER BRACKET @\$77.10 (CONSISTENT) | NOT NECESSARY | 385.50 | - |
| 1 | REAR BUMPER (LOWER) (CONSISTENT) | DEFORMED | 284.50 | 284.50 |
| 2 | REAR BUMPER LAMP @\$130.70 (CONSISTENT) | NOT NECESSARY | 261.40 | - |
| 2 | REAR BUMPER SIDE RETAINER @\$39.20 (CONSISTENT) | NECESSARY | 78.40 | 78.40 |
| 1 | REAR BUMPER REINFORCEMENT (CONSISTENT) | CRACKED | 672.60 | 612.60 |
| 2 | REAR BUMPER REINFORCEMENT BRACKET @\$29.20 (CONSISTENT) | NOT NECESSARY | 58.40 | - |
| 2 | REAR NUMBER PLATE LAMP @\$67.10 (CONSISTENT) | NOT NECESSARY | 134.20 | - |
| 2 | TAIL LAMP @\$1108.50 (CONSISTENT) | NOT NECESSARY | 2,217.00 | - |
| 2 | REAR FENDER INNER COWLING @\$96.30 (CONSISTENT) | NOT NECESSARY | 192.60 | - |
| 2 | REAR FENDER INNER TRIM @\$236.30 (CONSISTENT) | NOT NECESSARY | 472.60 | - |

Report Ref No. CC4/ASM20011760/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------------------|-------------------------------|-------------------|
| 1 | TAILGATE INNER LOCK (CONSISTENT) | NOT NECESSARY | 148.40 | - |
| 1 | TAILGATE LOCK BOTTOM (CONSISTENT) | NOT NECESSARY | 21.30 | - |
| 1 | TAILGATE DETECTOR (CONSISTENT) | NOT NECESSARY | 169.10 | - |
| 1 | TAILGATE WEATHERSTRIP (CONSISTENT) | NOT NECESSARY | 138.70 | - |
| 1 | REAR END PANEL (CONSISTENT) | DENTED | 499.30 | 499.30 |
| 1 | REAR END PANEL TOP GARNISH (CONSISTENT) | DEFORMED | 97.40 | 97.40 |
| 1 | REAR FLOOR PANEL (CONSISTENT) | NOT NECESSARY | 966.80 | - |
| 1 | REAR FLOOR TOP BOARD (CONSISTENT) | NOT NECESSARY | 187.10 | - |
| 1 | REAR SPARE TYRE BOLT (CONSISTENT) | NOT NECESSARY | 24.00 | - |
| 1 | REAR TOOLS SPONGE (CONSISTENT) | NOT NECESSARY | 126.10 | - |
| 1 | REAR EXHAUST PIPE (CONSISTENT) | NOT NECESSARY | 1,446.20 | - |
| 1 | REAR EXHAUST CHROME PIPE (CONSISTENT) | NOT NECESSARY | 304.40 | - |
| 1 | REAR EXHAUST INSULATOR (CONSISTENT) | NOT NECESSARY | 260.10 | - |
| 4 | REAR EXHAUST MOUNTING @\$29.20 (CONSISTENT) | NOT NECESSARY | 116.80 | - |
| 4 | REAR REVERSE SENSOR @\$178.20 (CONSISTENT) | DAMAGED (2 PCS ONLY) | 712.80 | 356.40 |
| 4 | REAR REVERSE SENSOR HOLDER @\$42.60 (CONSISTENT) | NECESSARY (2 PCS ONLY) | 170.40 | 85.20 |
| | LESS 20% DISCOUNT | | -3,613.46 | -1,180.88 |
| | | | 14,453.84 | 4,723.52 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT NUMBER PLATE (SN) (CONSISTENT) | BENT | 80.00 | 30.00 |
| 1 | SET FRONT BUMPER CLIP (SN) (CONSISTENT) | NECESSARY | 80.00 | 30.00 |
| 1 | SET FRONT FENDER COWLING CLIP (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | FRONT SUPPORT TOP PANEL SEALANT (SN) (CONSISTENT) | NOT NECESSARY | 120.00 | - |
| 1 | COOLANT (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | REAR NUMBER PLATE (SN) (CONSISTENT) | BENT | 80.00 | 60.00 |
| 1 | SET REAR BUMPER CLIP (SN) (CONSISTENT) | NECESSARY | 80.00 | 30.00 |
| 1 | SET TAILGATE INNER LOWER TRIM CLIP (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | SET TAILLAMP CLIP (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | - |
| 1 | SET REAR FENDER INNER TRIM CLIP (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |

Report Ref No. CC4/ASM20011760/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|-------------------|
| 1 | SET REAR FENDER INNER COWLING CLIP (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | REAR END PANEL INSULATION SEAL (SN) (CONSISTENT) | NECESSARY | 150.00 | 60.00 |
| 1 | SET REAR END PANEL TOP GARNISH CLIP (SN) (CONSISTENT) | NECESSARY | 50.00 | 20.00 |
| 1 | REAR FLOOR PANEL INSULATION SEAL (SN) (CONSISTENT) | NOT NECESSARY | 450.00 | - |
| 1 | TRIANGLE BREAKDOWN SIGN (SN) (CONSISTENT) | NOT NECESSARY | 180.00 | - |
| | | | 1,700.00 | 230.00 |
| | <u>LABOUR</u> | | | |
| | TO PANEL BEAT ,REMOVE AND REPLACE PARTS. | | 1,000.00 | 300.00 |
| | TO SPRAY PAINT AFFECTED AREA . | | 1,000.00 | 250.00 |
| | REFOCUS HEADLAMP BEAM . | NOT NECESSARY | 80.00 | - |
| | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC. | NOT NECESSARY | 180.00 | - |
| | TO PANEL BEAT ,REMOVE AND REPLACE PARTS. | | 1,400.00 | 600.00 |
| | TO SPRAY PAINT AFFECTED AREA . | | 1,400.00 | 600.00 |
| | TUFF COAT. | | 250.00 | 60.00 |
| | WIRING AND BULB CHECK. | | 180.00 | 30.00 |
| | REMOVE AND REFIX CUSHION SEAT /UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR. | | 350.00 | 60.00 |
| | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING. | | 80.00 | 50.00 |
| | CONDUCT WATER LEAKAGE TEST . | NOT NECESSARY | 120.00 | - |
| | REMOVE AND REFIX REAR EXHAUST PIPE . | | 180.00 | |
| | | | 6,220.00 | 1,950.00 |
| | GRAND TOTAL | | 22,373.84 | 6,903.52 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 5,500.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CC4/ASM20011760/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.