

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011762/KRA3Q2
Date: 28/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070112668
Claimant Vehicle No :	SLH5515P	Insured Vehicle No :	SLA6669J
Date of Loss:	25/10/2020	Nature of Claim:	TP
		Claim No:	6918056878SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH5515P		
Make & Model:	HONDA STREAM, 1.8 L (A)	Engine No:	R18A1729510
Reg. Date:	05/03/2007 (Man. Year: 2007)	Chassis No:	RN61026163
Colour:	Black	Odometer:	290260 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,079.28	4,023.27	3,056.01	43.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,200.00	1,180.00	34.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,459.28	6,223.27	4,236.01	40.50
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	10,459.28	5,000.00	5,459.28	52.20
+ GST 7.00/7.00% (S\$)	732.15	350.00	382.15	52.20
Nett Amount (S\$)	11,191.43	5,350.00	5,841.43	52.20
+ Car Rental (8.0 x S\$120.00/day + 7.00% GST) (S\$)		1,027.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,379.20		
Global Sum Settlement (S\$)		6,400.00		

INSPECTION

Date of Assignment: 28/10/2020

Date Inspected: 29/10/2020

Inspected At:

Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	956.00 FL	*956.00 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	57.00 FL	*57.00 FL
3	1		*TAILGATE LOCK	Jammed	115.00 FL	*115.00 FL
4	1		*TAILGATE WEATHERSTRIP (50%)	Dented / Deformed	102.96 FS	*64.35 FS
5	1		*TAILGATE TRIM BOARD	Mtg Distorted	150.00 FL	*150.00 FL
6	12		*TAILGATE TRIM BOARD CLIPS	Necessary	45.60 FL	*45.60 FL
7	1		*TAILGATE INNER HANDLE GRIP	Missing	26.00 FL	*26.00 FL
8	1		*TAILGATE STOPPER RH	Missing	8.90 FL	*8.90 FL
9	1		*TAILLAMPS	N/S Cracked	978.40 FL	*489.20 FL
10	1		*REAR BUMPER	Bent	599.00 FL	*599.00 FL
11	2		*REAR BUMPER BRACKETS	Repair	31.00 FL	*- FL
12	12		*REAR BUMPER CLIPS	Necessary	45.60 FL	*45.60 FL
13	1		*REAR BUMPER TOW COVER	Missing	14.20 FL	*14.20 FL
14	1		*END PANEL	Bent	325.00 FL	*325.00 FL
15	1		*END PANEL INNER PANEL	Bent	472.00 FL	*472.00 FL
16	1		*END PANEL GARNISH	Mtg Cracked	123.00 FL	*123.00 FL
17	1		*END PANEL GARNISH CENTER JACK COVER	Distorted	145.20 FL	*145.20 FL
18	1		*REAR TYRE JACK	Repair	132.00 FL	*- FL
19	1		*REAR FENDER TRIM BOARD	Cracked	297.40 FL	*297.40 FL
20	1		*SPARE TYRE PANEL	Repair	1,062.60 FL	*- FL
21	1		*SPARE TYRE PANEL INSULATION	Necessary	152.00 FS	*60.00 FS
22	2		*REAR TRUNK SPARE TOP BOARDS	Dented	260.80 FL	*260.80 FL
23	1		*REAR EXHAUST SILENCER	Repair	780.00 FL	*- FL
24	1		*REAR EXHAUST SILENCER GASKET	Serviceable	18.20 FL	*- FL
25	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
26	1		*TAILGATE GLASS SEALER	Necessary	30.00 FS	*30.00 FS
27	1		*TAILGATE GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
28	1		*TAILGATE EMBLEM STICKER	Not Necessary	55.00 FS	*- FS
29	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
30	1		*REAR BUMPER REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
31	1		*REAR REVERSE CAMERA	Dented	250.00 FS	*250.00 FS
32	1		*IN CAR DASH CAMERA (FRONT & REAR TYPE)	Serviceable	750.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,407.86	4,849.25
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,328.58	825.98

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	7,079.28
						4,023.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /TRANSFER TAILGATE FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
2	TO DISMANTLE /REFIT TAILGATE GLASS	New	160.00	120.00
3	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS & TRIMS	New	80.00	60.00
4	TO CONDUCT ELECTRICAL CHECK ,REPLACE REVERSE CAMERA ,SENSORS ,MODULE REWIRING ETC	New	120.00	60.00
5	TO SUPPLY REAR BODY PANEL SEALANT	New	80.00	30.00
6	TO DISMANTLE /REFIT REAR BOOT SPOILER ,SUPPLY ADHESIVE DOUBLE SIDED TAPE ,DRILLING ETC	New	90.00	50.00
7	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	100.00	60.00
8	TO DISMANTLE /REPAIR EXHAUST SILENCER	New	100.00	60.00
9	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF REAR CHASSIS MEMBER,INNER PANEL ,FLOOR PANEL ETC .CNT ,WELD END PANEL AND PARTS REPLACEMENT	New	1,500.00	900.00
10	TO RESPRAY AFFECTED AREAS	New	1,000.00	800.00
Gross Labour Cost (\$\$)			3,380.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >