

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20011765/QSD3E2**Date:** 12/08/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100473412
Claimant Vehicle No :	SG5085K	Insured Vehicle No :	SLD8391E
Date of Loss:	21/10/2020	Nature of Claim:	TP
		Claim No:	9286475257SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5085K	Engine No:	D9195111
Make & Model:	VOLVO B9TL, 9.4 D AUTO TURBO ABS (A)	Chassis No:	YV3S4P925GA177367
Reg. Date:	23/05/2016 (Man. Year: 2015)	Odometer:	261716 km
Colour:	Multi-colour		
Engine Capacity:	9364 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	731.00	731.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	742.00	550.00	192.00	25.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,473.00	1,281.00	192.00	13.03
+ GST 7.00/7.00% (S\$)	103.11	89.67	13.44	13.03
Nett Amount (S\$)	1,576.11	1,370.67	205.44	13.03

INSPECTION

Date of Assignment:	26/10/2020		
Date Inspected:	28/10/2020	Inspected At:	SBS Transit Ltd (YCK) 3 Yio Chu Kang Crescent Singapore 786010
Estimated Period of Repair:	2.0 days		

Adjuster: OI SUN PIN**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*PANEL ATTACHMENT BRKT;SHEETMETAL	Bent	27.00 F	*27.00 F
2	4		*M8X16 ALLEN HEAD BOLT PATCHED	Necessary	7.00 F	*7.00 F
3	1		*SIDE SHEETMETAL PANEL	Bent	689.00 F	*689.00 F
4	1		*SPRAY GREEN 400ML	Necessary	8.00 F	*8.00 F
F=Franchise part.						
Total Parts (S\$)					731.00	731.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	(2) WORKSHOP LABOUR	New	192.00	0.00
2	CONTRACTORS REPAIR CHARGES	New	550.00	550.00
Gross Labour Cost (S\$)			742.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >