

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011766/KQF3E2

Date: 03/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00059342001
Claimant Vehicle No: SKX2642C Insured Vehicle No: YN8896J
Date of Loss: 26/10/2020 Nature of Claim: TP Claim No: SNM20D204075/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX2642C
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4022699
Reg. Date: 01/12/2015 (Man. Year: 2015) Chassis No: RU11102696
Colour: Metallic Dark Blue Odometer: 162717 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,177.36	2,938.72	3,238.64	52.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	1,240.00	1,200.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	8,617.36	4,178.72	4,438.64	51.51
+ GST 7.00/7.00% (\$\$)	603.22	292.51	310.71	51.51
Nett Amount (\$\$)	9,220.58	4,471.23	4,749.35	51.51

INSPECTION

Date of Assignment: 28/10/2020
Date Inspected: 28/10/2020 Inspected At: K Kim Hin Auto Pte Ltd
BLK 34 SIN MING DRIVE, #01-114,
Singapore 575708
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2642C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Cut	459.80 FL	*459.80 FL
2	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Serviceable	35.00 FL	*- FL
3	2		*REAR BUMPER SIDE COVER (LH/RH)	Serviceable	390.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
5	2		*REAR WHEEL ARCH GARNISH (LH/RH)	Serviceable	300.00 FL	*- FL
6	1		*REAR END PANEL	Repair	411.90 FL	*- FL
7	1		*REAR END PANEL TOP GARNISH	Serviceable	92.30 FL	*- FL
8	1		*TAILGATE	Bent	1,050.00 FL	*1,050.00 FL
9	2		*TAILGATE HINGES (LH/RH)	Repair	100.00 FL	*- FL
10	2		*TAILGATE DAMPER (LH/RH)	Serviceable	360.00 FL	*- FL
11	1		*TAILGATE OUTER GARNISH	Mtg Cracked	189.90 FL	*189.90 FL
12	1		*TAILGATE OUTER HANDLE	Serviceable	175.50 FL	*- FL
13	1		*TAILGATE LOGO	Not Necessary	15.40 FL	*- FL
14	1		*TAILGATE VEZEL EMBLEM	Necessary	43.00 FL	*43.00 FL
15	1		*TAILGATE LOCK	Dented	157.10 FL	*157.10 FL
16	1		*TAILGATE LOCK CATCH	Repair	27.50 FL	*- FL
17	1		*TAILGATE WEATHERSTRIP	Serviceable	96.80 FL	*- FL
18	2		*TAILGATE LAMP (LH/RH)	Cut	553.80 FL	*553.80 FL
19	1		*TAILGATE INNER TRIMBOARD-BOTTOM	Serviceable	153.40 FL	*- FL
20	1		*TAILGATE INNER HANDLE POCKET	Serviceable	25.00 FL	*- FL
21	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	120.00 FL	*120.00 FL
22	1		*REAR EXHAUST MUFFLE	Repair	528.00 FL	*- FL
23	2		*TAILLAMP ASSY (LH/RH)	Cut	964.80 FL	*964.80 FL
24	1		*REAR BUMPER TOTAL LOGO STICKER	Necessary	200.00 FS	*20.00 FS
25	1		*REAR END PANEL TOP GARNISH CHROME	Serviceable	250.00 FS	*- FS
26	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
27	1		*TAILGATE WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
28	1		*REVERSE SENSOR	Serviceable	220.00 FS	*- FS
29	1		*REVERSE CAMERA	Serviceable	380.00 FS	*- FS
30	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,434.20	3,653.40
- List Item Discount on L Items 20.00/20.00% (\$)	1,256.84	714.68
Total Parts (\$)	6,177.36	2,938.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	750.00	500.00
2	TO FOCUS TAILLAMPS.TO CHECK REAR WIRING AND LIGHTING OPERATION	New	50.00	20.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
4	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING,ROOF LINING,SEATS,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	0.00
5	TO APPLY UNDERSEALING	New	120.00	30.00
6	TO TRANSFER TAILGATES FITTINGS	New	80.00	60.00
7	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	120.00	60.00
8	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	80.00	50.00
9	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,440.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >