

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011778/UBS3Q2
Date: 18/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900251641
Claimant Vehicle No :	SMA980L	Insured Vehicle No :	SKR1577X
Date of Loss:	27/10/2020	Nature of Claim:	TP
		Claim No:	7967982601SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA980L		
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Engine No:	D4FDJH553178
Reg. Date:	28/05/2018 (Man. Year: 2018)	Chassis No:	KNAHU815VJ7208508
Colour:	Black	Odometer:	152600 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Gaenlander 6 mm	Rear Left Side:	Gaenlander 6 mm
Front Right Side:	Gaenlander 6 mm	Rear Right Side:	Gaenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,458.40	2,233.80	4,224.60	65.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,790.00	710.00	28.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,958.40	4,023.80	4,934.60	55.08
Approved Total (Overridden) (S\$)		3,200.00		

(S\$)	8,958.40	3,200.00	5,758.40	64.28
+ GST 7.00/7.00% (S\$)	627.09	224.00	403.09	64.28
Nett Amount (S\$)	9,585.49	3,424.00	6,161.49	64.28
+ Loss of Use (4.0 x S\$25.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,526.00		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 29/10/2020

Date Inspected: 29/10/2020

Estimated Period of Repair: 4.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR DOOR	Repair	1,309.00 FL	*- FL
2	1		*O/S REAR DOOR LOCK	Not Necessary	229.00 FL	*- FL
3	2		*O/S REAR DOOR HINGE	Not Necessary	130.00 FL	*- FL
4	1		*O/S REAR DOOR TOP MOULDING	Not Necessary	85.00 FL	*- FL
5	1		*O/S REAR DOOR WEATHERSTRIP	Not Necessary	105.00 FL	*- FL
6	1		*O/S FRONT DOOR	Badly Dented / Warped	1,409.00 FL	*1,409.00 FL
7	1		*O/S FRONT DOOR OUTER HANDLE	Not Necessary	187.00 FL	*- FL
8	2		*O/S FRONT DOOR HINGE	Not Necessary	130.00 FL	*- FL
9	1		*O/S FRONT DOOR POWER WINDOW MOTOR	Not Necessary	310.00 FL	*- FL
10	1		*O/S FRONT DOOR POWER WINDOW REGULATOR	Not Necessary	229.00 FL	*- FL
11	1		*O/S FRONT DOOR WEATHERSTRIP	Not Necessary	105.00 FL	*- FL
12	1		*O/S FRONT DOOR TOP MOULDING	Necessary	85.00 FL	*85.00 FL
13	1		*O/S FRONT FENDER	Repair	1,223.00 FL	*- FL
14	1		*O/S SIDE MIRROR ASSY	Repair	652.00 FL	*- FL
15	1		*O/S ROCKER PANEL	Dented / Bent	988.00 FL	*988.00 FL
					Sub Total (\$\$)	7,176.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	717.60
					Total Parts (\$\$)	6,458.40
						2,482.00
						2,233.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE OF O/S FRONT AND REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	200.00	60.00
2	TO REPLACE O/S SIDE MIRROR	New	50.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,100.00	800.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	900.00
Gross Labour Cost (\$)			2,500.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >