

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1620011778/4653

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMA 980C

at Workshop m/s Tan Lim

of _____

Insured: SKR1577X

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 70k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 980C Yr Regn: 5,18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: KIA carents c.c. 1685

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 152600 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAHU815VJ7208508

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or garen/onder

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/10/20

D.O.I. 29/10/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Involved LTA # 42953

29/10/20 confirmed n/s # 3200 with willian

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

TOTAL

not fulfill
all
d/s # 3200
4 days
The gl. & the rep
28/10/20



Messrs BIS Motoring Pte Ltd

Date : 28 October 2020

pen: like -marcs

29/10/2020 01020h

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	o/s rear door <i>n</i>	\$ 1,309.00
02	1 pc	o/s rear door lock <i>u u</i>	\$ 229.00
03	2 ps	o/s rear door hinge @ \$65.00 <i>u u</i>	\$ 130.00
04	1 pc	o/s rear door top moulding <i>u u</i>	\$ 85.00
05	1 pc	o/s rear door weatherstrip <i>u u</i>	\$ 105.00
06	1 pc	o/s front door <i>30/500 / moped</i>	\$ 1,409.00
07	1 pc	o/s front door outer handle <i>u u</i>	\$ 187.00
08	2 ps	o/s front door hinge @ \$65.00 <i>u u</i>	\$ 130.00
09	1 pc	o/s front door power window motor <i>u u</i>	\$ 310.00
10	1 pc	o/s front door power window regulator <i>u u</i>	\$ 229.00
11	1 pc	o/s front door weatherstrip <i>u u</i>	\$ 105.00
12	1 pc	o/s front door top moulding <i>u u</i>	\$ 85.00
13	1 pc	o/s front fender <i>n</i>	\$ 1,223.00
14	1 pc	o/s side mirror assy <i>n</i>	\$ 652.00
15	1 pc	o/s rocker panel <i>u / Bent</i>	\$ 988.00
			\$ 7,176.00
		Less 10 %	\$ 717.60
			\$ 6,458.40
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of o/s front and rear door fittings and perform water seepage test.	\$ 200.00
02		To replace o/s side mirror.	\$ <i>u u</i> 50.00
03		To rust-proofing of the affected areas.	\$ 150.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,100.00
05		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,500.00
		Total	\$ 8,958.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: