

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011784/AGA3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070071861	
Claimant Vehicle No : YP2222H	Insured Vehicle No : YP2570C	
Date of Loss: 27/10/2020	Nature of Claim: TP	Claim No: 0503080977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YP2222H		
Make & Model: ISUZU NPR75UH5A, 5.2 D (M)	Engine No: 4HK1431366	
Reg. Date: 12/02/2016 (Man. Year: 2015)	Chassis No: JAANPR75HF7106453	
Colour: White	Odometer: 185614 km	
Engine Capacity: 5193 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17	Rear Tyre Size: 215/75 R17	
Front Left Side: Compasal 6 mm	Rear Left Side: Compasal 6 mm	
Front Right Side: Compasal 6 mm	Rear Right Side: Compasal 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,590.68	11,958.31	25,632.37	68.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,890.00	1,880.00	4,010.00	68.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,480.68	13,838.31	29,642.37	68.17
Approved Total (Overridden) (S\$)		11,000.00		
(S\$)	43,480.68	11,000.00	32,480.68	74.70
+ GST 7.00/7.00% (S\$)	3,043.65	770.00	2,273.65	74.70
Nett Amount (S\$)	46,524.33	11,770.00	34,754.33	74.70
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		50.45		
Nett Liability (S\$)		12,820.45		

INSPECTION

Date of Assignment: 28/10/2020		
Date Inspected: 29/10/2020	Inspected At:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair: 10.0 days		

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	2	*TAIL LAMP	Cracked	368.60 FL	*368.60 FL
2	1	*REAR NUMBER PLATE LAMP	Not Necessary	67.50 FL	*- FL
3	1	*TAIL GATE 60KM STICKER	Necessary	40.00 FS	*15.00 FS
4	1	*TAILGATE WOODEN (SPECIAL TYPE)	Cracked	2,800.00 FS	*1,200.00 FS
5	4	*TAILGATE HINGE (SPECIAL TYPE)	Bent	720.00 FS	*720.00 FS
6	1	*TAILGATE STICKER JOTUN	Necessary	120.00 FS	*80.00 FS
7	1	*TAILGATE LATTERIG KAI LIM	Necessary	180.00 FS	*60.00 FS
8	1	*TAILGATE LATTERIG KAI LIM	Necessary	250.00 FS	*80.00 FS
9	1	*TAILGATE LATTERIG 67423333	Necessary	200.00 FS	*60.00 FS
10	1	*REAR STEP BEAM (SPECIAL TYPE)	Cracked	1,200.00 FS	*350.00 FS
11	1	*REAR CARGO BED REAR FRAME (SPECIAL TYPE)	Repair	1,800.00 FS	*- FS
12	1	*REAR CARGO BED PLAFROM (WOODEN) (9 PCS)	Cracked (2 PCS ONLY)	7,200.00 FS	*1,600.00 FS
13	1	*REAR CARGO BED BOTTOM BEAMS (SPECIAL TYPE) (9 PCS)	Cracked (4 PCS ONLY)	7,200.00 FS	*2,400.00 FS
14	2	*CARGO BED CHASSIS MEMBER (WOODEN)	Cracked	11,600.00 FS	*2,800.00 FS
15	1	*CARGO BED REAR CROSS MEMBER (WOODEN)	Cracked	1,800.00 FS	*1,000.00 FS
16	1	*CARGO BED U CLIP (4 PCS)	Necessary (4 PCS ONLY)	1,500.00 FS	*800.00 FS
17	1	*CARGO BED END STICKER (ORANGE & WHITE)	Necessary	80.00 FS	*50.00 FS
18	1	*CARGO BED END STICKER (YELLOW & BACK)	Necessary	80.00 FS	*50.00 FS
19	1	*REVERSE CAMERA	Damaged	450.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	37,656.10	12,013.60
- List Item Discount on L Items 15.00/15.00% (S\$)	65.42	55.29
Total Parts (S\$)	37,590.68	11,958.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,KNOCK ,WELD ,CUT ,ADJUST ,STRAIGHTEN ,GRAZE ,ALIGN	New	1,200.00	500.00
2	TO PUTTY ,SPRAY PAINT ,POLISH WAX	New	1,200.00	500.00
3	BULB CHECKING WIRING	New	180.00	30.00
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
5	REAR CHASSIS ALIGNMENT	New	250.00	0.00
6	TO REMOVE /REFIX CARGO BED	New	2,800.00	800.00
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			5,890.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >