

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 28.10.20

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **YP2222H**
MODEL : ISUZU NPR75UH5A
DATE OF ACCIDENT : 27.10.20
TIME OF ACCIDENT : 15:10HRS

Cecilia

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP <i>cracked</i>	2	\$ 184.30	\$ 368.60
2	REAR NUMBER PLATE LAMP <i>Not in</i>	1	\$ 67.50	\$ 67.50

368.60

313.31

TOTAL PRICE \$ 436.10
LESS 15% \$ 65.42
SUB TOTAL PRICE \$ 370.69

CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAIL GATE '60KM STICKER <i>NEC</i>	1	\$ 40.00	\$ 40.00
2	TAILGATE WOODEN (SPECIAL TYPE) <i>cracked</i>	1	\$ 2,800.00	\$ 2,800.00
3	TAILGATE HINGE (SPECIAL TYPE) <i>Not in Best</i>	4	\$ 180.00	\$ 720.00
4	TAILGATE STICKER 'JOTUN' <i>NEC</i>	1	\$ 120.00	\$ 120.00
5	TAILGATE LATTERIG 'KAI LIM' <i>NEC</i>	1	\$ 180.00	\$ 180.00
6	TAILGATE LATTERIG '奎林' <i>in</i>	1	\$ 250.00	\$ 250.00
7	TAILGATE LATTERIG '67423333' <i>in</i>	1	\$ 200.00	\$ 200.00
8	REAR STEP BEAM (SPECIAL TYPE) <i>cracked</i>	1	\$ 1,200.00	\$ 1,200.00
9	REAR CARGO BED REAR FRAME (SPECIAL TYPE) <i>in</i>	1	\$ 1,800.00	\$ 1,800.00
10	REAR CARGO BED PLAFROM (WOODEN) <i>2 pieces cracked</i>	9	\$ 800.00	\$ 7,200.00
11	REAR CARGO BED BOTTOM BEAMS (SPECIAL TYPE) <i>cracked 4 pieces</i>	9	\$ 800.00	\$ 7,200.00
12	CARGO BED CHASSIS MEMBER (WOODEN) <i>cracked</i>	2	\$ 5,800.00	\$ 11,600.00
13	CARGO BED REAR CROSS MEMBER (WOODEN) <i>cracked</i>	1	\$ 1,800.00	\$ 1,800.00
14	CARGO BED U CLIP <i>4 pieces NEC</i>	6	\$ 250.00	\$ 1,500.00
15	CARGO BED END STICKER (ORANGE & WHITE) <i>in</i>	1	\$ 80.00	\$ 80.00
16	CARGO BED END STICKER (YELLOW & BACK) <i>in</i>	1	\$ 80.00	\$ 80.00
17	REVERSE CAMERA <i>Don't</i>	1	\$ 450.00	\$ 450.00

TOTAL \$ 37,220.00

11645

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **YP2222H**
MODEL : **ISUZU NPR75UH5A**
DATE OF ACCIDENT : 27.10.20
TIME OF ACCIDENT : 15:10HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 1,200.00	500-
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,200.00	500
3	BULB CHECKING, WIRING	\$ 180.00	30
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
5	REAR CHASSIS ALIGNMENT	\$ 250.00	x. 800
6	TO REMOVE / REFIX CARGO BED	\$ 2,800.00	800
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

5,890.00

1880

TOTAL PARTS COST : \$ 37,590.69
TOTAL LABOUR COST : \$ 5,890.00
TOTAL REPAIR COST : \$ 43,480.69

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian L. total: 13838-31
L/s 29/10/20 L/s: 11K
10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: