

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI20011802/ESD3Q2

**Date:** 04/11/2020

### REFERENCE

|                                                        |                                        |
|--------------------------------------------------------|----------------------------------------|
| Handling Insurer: Tokio Marine Insurance Singapore Ltd | Policy No: MC001737                    |
| <b>Claimant</b>                                        |                                        |
| <b>Vehicle No :</b> SH8965X                            | <b>Insured Vehicle No :</b> YN1071T    |
| Date of Loss: 29/10/2020                               | Nature of Claim: TP Claim No: M2005336 |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | SH8965X                               | Engine No:  | G4LEKU411495      |
| Make & Model:               | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Chassis No: | KMHC851CVLU190742 |
| Reg. Date:                  | 06/08/2020 (Man. Year: 2019)          | Odometer:   | 18876 km          |
| Colour:                     | Blue                                  |             |                   |
| Engine Capacity:            | 1580 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |      |
|--------------------------|------|-------------------------|-----|--------------------------|------|
| General Condition:       | Good | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes  |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  | Good |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65R15     | Rear Tyre Size:  | 195/65/R15    |
| Front Left Side:  | Goodyear 5 mm | Rear Left Side:  | Goodyear 5 mm |
| Front Right Side: | Goodyear 5 mm | Rear Right Side: | Goodyear 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                 | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                          | 5,352.88        | 3,831.68        | 1,521.20        | 28.42        |
| Miscellaneous Items            | 11.00           | 11.00           | 0.00            | 0.00         |
| Labour                         | 1,560.00        | 1,250.00        | 310.00          | 19.87        |
| Paintwork Labour               | 0.00            | 0.00            | 0.00            |              |
| Towing                         | 0.00            | 0.00            | 0.00            |              |
| <b>Gross Total (\$\$)</b>      | <b>6,923.88</b> | <b>5,092.68</b> | <b>1,831.20</b> | <b>26.45</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b> | <b>484.67</b>   | <b>356.49</b>   | <b>128.18</b>   | <b>26.45</b> |
| <b>Nett Amount (\$\$)</b>      | <b>7,408.55</b> | <b>5,449.17</b> | <b>1,959.38</b> | <b>26.45</b> |

### INSPECTION

|                             |                              |                                                                                   |
|-----------------------------|------------------------------|-----------------------------------------------------------------------------------|
| Date of Assignment:         | 30/10/2020 Present Location: | ComfortDelGro Engineering Pte Ltd (Loyang)                                        |
| Date Inspected:             | 29/10/2020 Inspected At:     | ComfortDelGro Engineering Pte Ltd (Loyang)<br>59 Loyang Drive<br>Singapore 508969 |
| Estimated Period of Repair: | 3.0 days                     |                                                                                   |

**Adjuster:** CHEN TSUE YEE

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                        |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 04 Nov 2020)                          |
| <b>Parts:</b>        | 192                                                                                                                                                                          | HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                      |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SH8965X)                                                                                                                                     |                                                                        |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                        |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                        |

### Recommended Parts

| No.                     | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Reference | Amount       |
|-------------------------|-----|----------|---------------------------------------|---------------|-------------|-----------|--------------|
| 1                       | 1   |          | *REAR BUMPER                          | Dented        | 459.40 FL   | -         | *459.40 FL   |
| 2                       | 1   |          | *REAR BUMPER REINFORCEMENT            | Broken        | 294.80 FL   | -         | *294.80 FL   |
| 3                       | 2   |          | *REAR BUMPER REINFORCEMENT BRKT RH/LH | Not Necessary | 276.20 FL   | -         | *- FL        |
| 4                       | 1   |          | *REAR BUMPER CENTER MOULDING          | Broken        | 451.25 FL   | -         | *451.25 FL   |
| 5                       | 1   |          | *REAR BUMPER LOWER MOULDING           | Not Necessary | 155.00 FL   | -         | *- FL        |
| 6                       | 2   |          | *REAR BUMPER SIDE BRKT RH/LH          | Not Necessary | 111.60 FL   | -         | *- FL        |
| 7                       | 10  |          | *REAR BUMPER CLIPS                    | Necessary     | 22.00 FL    | -         | *22.00 FL    |
| 8                       | 1   |          | *REAR BUMPER UNDER CENTER COVER       | Not Necessary | 225.00 FL   | -         | *- FL        |
| 9                       | 2   |          | *REAR BUMPER SIDE COVER RH/LH         | Not Necessary | 216.00 FL   | -         | *- FL        |
| 10                      | 1   |          | *REAR BUMPER TOW COVER                | Not Necessary | 5.40 FL     | -         | *- FL        |
| 11                      | 1   |          | *REAR BUMPER REFLECTOR RH             | Not Necessary | 31.90 FL    | -         | *- FL        |
| 12                      | 1   |          | *REAR BUMPER FOGLAMP                  | Broken        | 201.50 FL   | -         | *201.50 FL   |
| 13                      | 1   |          | *BOOTLID                              | Dented        | 2,480.40 FL | -         | *2,480.40 FL |
| 14                      | 1   |          | *BOOTLID EMBLEM-H                     | Necessary     | 28.00 FL    | -         | *28.00 FL    |
| 15                      | 1   |          | *BOOTLID EMBLEM-HYBRID                | Necessary     | 24.30 FL    | -         | *24.30 FL    |
| 16                      | 1   |          | *BOOTLID EMBLEM-IONIQ                 | Necessary     | 31.30 FL    | -         | *31.30 FL    |
| 17                      | 1   |          | *BOOTLID SPOILER                      | Not Necessary | 655.40 FL   | -         | *- FL        |
| 18                      | 1   |          | *BOOTLID BLACK GLASS                  | Cut           | 384.90 FL   | -         | *384.90 FL   |
| 19                      | 1   |          | *BOOTLID COMFORTDELGRO & 65521111     | Necessary     | 60.00 F     | -         | *60.00 FS    |
| 20                      | 1   |          | *BOOTLID APPS                         | Necessary     | 40.00 F     | -         | *40.00 FS    |
| 21                      | 1   |          | *REVERSE SENSOR                       | Not Necessary | 180.00 F    | -         | *- FS        |
| 22                      | 2   |          | *WINDSCREEN GLASSES SEALANT           | Necessary     | 92.00 F     | -         | *92.00 FS    |
| 23                      | 1   |          | *REAR NO.PLATE WITH TRIM COVER        | Broken        | 55.00 F     | -         | *55.00 FS    |
| <b>Supplementary #1</b> |     |          |                                       |               |             |           |              |
| 24                      | 1   |          | *SMART KEY ANTENNA                    | Broken        | 40.50 FL    | -         | *40.50 FL    |
| 25                      | 1   |          | *REAR BUMPER MAT                      | Necessary     | 50.00 F     | -         | *50.00 F     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,571.85</b> | <b>4,715.35</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | <b>1,218.97</b> | <b>883.67</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>5,352.88</b> | <b>3,831.68</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars          | Repairer's   | Amount       |
|----------------------------|-----|----------------------|--------------|--------------|
| <b>Miscellaneous Items</b> |     |                      |              |              |
| 1                          | 1   | OD/TP Case (Insurer) | 11.00        | 11.00        |
| <b>Sub Total (\$\$)</b>    |     |                      | <b>11.00</b> | <b>11.00</b> |

## Recommended Labour

| No                              | Particulars              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                          |          |                 |                 |
| 1                               | PANEL BEATING            | New      | 700.00          | 640.00          |
| 2                               | SPRAY PAINTING           | New      | 500.00          | 400.00          |
| 3                               | CHECK LIGHTINGS / WIRING | New      | 40.00           | 30.00           |
| 4                               | R/I BOOTLID GLASSES      | New      | 200.00          | 150.00          |
| 5                               | R/I REVERSE SENSOR       | New      | 120.00          | 30.00           |
| <b>Gross Labour Cost (\$\$)</b> |                          |          | <b>1,560.00</b> | <b>1,250.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >