

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011803/GEA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No :	FBJ928Y	Insured Vehicle No :	SHC2822X	
Date of Loss:	29/08/2020	Nature of Claim:	TP	Claim No: MCT20080473

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBJ928Y		Engine No:	E3J2E010194
Make & Model:	YAMAHA YBR125, 124cc (M)		Chassis No:	LBPKE1780D0014776
Reg. Date:	26/12/2013 (Man. Year: 2013)		Odometer:	61935 km
Colour:	Blue			
Engine Capacity:	124 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	3.00-18
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,699.20	2,296.90	1,402.30	37.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	890.00	230.00	660.00	74.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,589.20	2,526.90	2,062.30	44.94
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	4,589.20	2,000.00	2,589.20	56.42
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		2,060.00		

INSPECTION

Date of Assignment:	29/10/2020	The Sincere Motor Repairing Pte Ltd (HQ) No. 2 Kallang Avenue Blk 3 #01-128/130 Kallang Avenue Industrial Centre Singapore 339407
Date Inspected:	29/10/2020 Inspected At:	
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 May 2022)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBJ928Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP ASSY	Cut	178.00 FL	*178.00 FL
2	1		*SET HANDLE GRIP	Not Necessary	30.00 FL	*- FL
3	1		*HEAD LIGHT COWLING	Cracked	138.00 FL	*108.00 FL
4	1		*HEAD LIGHT STAY	Bent	89.00 FL	*89.00 FL
5	1		*BRAKE LEVER	Broken	29.50 FL	*29.50 FL
6	1		*HANDLE BAR	Bent	95.00 FL	*75.00 FL
7	1		*HANDLE BAR CROWN	Not Necessary	118.00 FL	*- FL
8	1		*CUSHION SEAT	Cut	165.00 FL	*125.00 FL
9	1		*FORK TOP BRIDGE	Bent	112.00 FL	*112.00 FL
10	1		*CLUTCH LEVER	Cut	29.50 FL	*29.50 FL
11	1		*METER ASSY	Cut	385.00 FL	*264.00 FL
12	1		*METER ASSY BRACKET	Not Necessary	43.00 FL	*- FL
13	1		*FRONT FENDER	Cut	168.00 FL	*120.00 FL
14	1		*FRONT WIND SHIELD	Cut	55.00 FL	*55.00 FL
15	2		*FRONT FORK ASSY	Bent	840.00 FL	*448.00 FL
16	1		*STEERING STEM WITH BEARING	Necessary	185.00 FL	*66.00 FL
17	1		*FOOT REST BAR	Bent	95.00 FL	*78.00 FL
18	1		*SET FOOT REST BAR RUBBER	Missing	25.00 FL	*25.00 FL
19	1		*REAR PILLION FOOT REST	Not Necessary	58.00 FL	*- FL
20	1		*REAR PILLION BRACKET (LH/RH)	N/S Not Necessary / O/S Bent	96.00 FL	*48.00 FL
21	2		*SIDE COVER (LH/RH)	Broken	156.00 FL	*128.00 FL
22	1		*EXHAUST	Not Necessary	290.00 FL	*- FL
23	1		*EXHAUST HEAT SHIELD	Cut	68.00 FL	*48.00 FL
24	1		*FUEL TANK	Dented	280.00 FL	*280.00 FL
25	2		*FUEL TANK AIR SCOOP COVER (LH/RH)	Broken	280.00 FL	*195.00 FL
26	2		*FUEL TANK AIR GUIDE COVER (LH/RH)	Broken	80.00 FL	*40.00 FL
27	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,108.00	2,551.00
- List Item Discount on L Items 10.00/10.00% (\$)	408.80	254.10
Total Parts (\$)	3,699.20	2,296.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN CHASSIS	New	450.00	0.00
2	TO DISMANTLE & ASSEMBLE PARTS FOR REPAIR	New	380.00	200.00
3	TOWING VEHICLE TO WORKSHOP	New	60.00	30.00
Gross Labour Cost (S\$)			890.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >