

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG20011805/AQD3Q2

**Date:** 25/11/2020

### REFERENCE

|                                                        |                             |                        |
|--------------------------------------------------------|-----------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900019835             |
| <b>Claimant</b>                                        |                             |                        |
| <b>Vehicle No :</b> SKE2537Z                           | <b>Insured Vehicle No :</b> | SMG6003L               |
| Date of Loss: 26/10/2020                               | Nature of Claim: TP         | Claim No: 9187655560SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |                               |
|-----------------------------|-----------------------------------|-------------------------------|
| Reg No:                     | <b>SKE2537Z</b>                   |                               |
| Make & Model:               | MERCEDES-BENZ C180, 1.8 (A)       | Engine No: 27182030414786     |
| Reg. Date:                  | 20/02/2012 (Man. Year: 2011)      | Chassis No: WDD2043492F831548 |
| Colour:                     | Black                             | Odometer: 137311 km           |
| Engine Capacity:            | 1796 cc                           |                               |
| Market Value/New Car Price: | N/A                               |                               |
| Sum Insured (\$):           | <b>Market Value/New Car Price</b> |                               |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/45R17        | Rear Tyre Size:  | 225/45R17        |
| Front Left Side:  | Continental 6 mm | Rear Left Side:  | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                   | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-----------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                   | 8,905.40          | 6,203.90          | 2,701.50          | 30.34         |
| Miscellaneous Items                     | 0.00              | 0.00              | 0.00              |               |
| Labour                                  | 2,580.00          | 1,510.00          | 1,070.00          | 41.47         |
| Paintwork Labour                        | 0.00              | 0.00              | 0.00              |               |
| Towing                                  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$)</b>      | <b>11,485.40</b>  | <b>7,713.90</b>   | <b>3,771.50</b>   | <b>32.84</b>  |
| <b>Approved Total (Overridden) (\$)</b> |                   | <b>6,000.00</b>   |                   |               |
| <b>Nett Amount (\$)</b>                 | <b>11,485.40</b>  | <b>6,000.00</b>   | <b>5,485.40</b>   | <b>47.76</b>  |

### INSPECTION

|                             |                          |                                                                                     |
|-----------------------------|--------------------------|-------------------------------------------------------------------------------------|
| Date of Assignment:         | 29/10/2020               |                                                                                     |
| Date Inspected:             | 29/10/2020 Inspected At: | Jec Automotive (HQ)<br>1 KAKI BUKIT AVENUE 6, #02-11<br>AUTOBAY<br>Singapore 417883 |
| Estimated Period of Repair: | 6.0 days                 |                                                                                     |

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT RH FENDER                          | Dented        | 925.00 FL   | *925.00 FL   |
| 2   | 1   |          | *FRONT RH FENDER INNER SHIELD             | Cut           | 198.00 FL   | *198.00 FL   |
| 3   | 1   |          | *FRONT RH FENDER CHROME MOULDING          | Necessary     | 45.00 FL    | *45.00 FL    |
| 4   | 1   |          | *FRONT RH FENDER BLUE EFFICIENCY EMBLEM   | Necessary     | 55.00 FL    | *55.00 FL    |
| 5   | 1   |          | *FRONT RH DOOR                            | Dented        | 2,739.00 FL | *2,075.00 FL |
| 6   | 1   |          | *FRONT RH DOOR LOCK                       | Not Necessary | 448.00 FL   | *- FL        |
| 7   | 1   |          | *FRONT RH DOOR WEATHERSTRIPE              | Necessary     | 289.00 FL   | *289.00 FL   |
| 8   | 2   |          | *FRONT RH DOOR HINGE                      | Not Necessary | 220.00 FL   | *- FL        |
| 9   | 1   |          | *FRONT RH DOOR CHECK                      | Not Necessary | 95.00 FL    | *- FL        |
| 10  | 1   |          | *FRONT RH DOOR LOWER CHROME MOULDING      | Necessary     | 128.00 FL   | *128.00 FL   |
| 11  | 1   |          | *FRONT RH DOOR INNER TRIM BOARD           | Not Necessary | 1,158.00 FL | *- FL        |
| 12  | 1   |          | *FRONT RH LOWER ARM                       | Bent          | 295.00 FL   | *295.00 FL   |
| 13  | 1   |          | *FRONT RH CONTROL ARM                     | Bent          | 245.00 FL   | *245.00 FL   |
| 14  | 1   |          | *FRONT RH KNUCKLE ARM                     | Damaged       | 674.00 FL   | *674.00 FL   |
| 15  | 1   |          | *FRONT RH WHEEL HUB C/W BEARING           | Damaged       | 395.00 FL   | *395.00 FL   |
| 16  | 1   |          | *FRONT RH WHEEL RIM                       | Cut           | 1,125.00 FS | *800.00 FS   |
| 17  | 1   |          | *SET FRONT RH FENDER INNER SHIELD CLIPS   | Necessary     | 30.00 FS    | *30.00 FS    |
| 18  | 1   |          | *SET FRONT RH DOOR INNER TRIM BOARD CLIPS | Not Necessary | 50.00 FS    | *- FS        |
| 19  | 1   |          | *FRONT RH SHOCK ABSORBER                  | Bent          | 647.00 FL   | *647.00 FL   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>9,761.00</b> | <b>6,801.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 855.60          | 597.10          |
| <b>Total Parts (\$\$)</b>                                  | <b>8,905.40</b> | <b>6,203.90</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                      |          |                 |                 |
| 1                              | PANEL BEATING,REMOVE AND REFIT PARTS | New      | 800.00          | 500.00          |
| 2                              | SPRAY PAINTING TO AFFECTED AREA      | New      | 1,000.00        | 600.00          |
| 3                              | WIRING CHECK                         | New      | 100.00          | 30.00           |
| 4                              | TO TRANSFER FRONT DOOR FITTINGS      | New      | 150.00          | 80.00           |
| 5                              | TO DISMANTLE FRONT UNDERCARRIAGE     | New      | 380.00          | 220.00          |
| 6                              | TO PERFORM WHEEL ALIGNMENT           | New      | 150.00          | 80.00           |
| <b>Gross Labour Cost (S\$)</b> |                                      |          | <b>2,580.00</b> | <b>1,510.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >