

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20011808/UBA3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700067649

Claimant
Vehicle No : SJX6138C **Insured Vehicle No :** SLT2046H

Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 4149897650SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX6138C	Engine No:	1AZE159747
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107054219
Reg. Date:	06/05/2010 (Man. Year: 2009)	Odometer:	221827 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,229.40	4,673.20	8,556.20	64.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,980.00	1,600.00	44.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,809.40	6,653.20	10,156.20	60.42
Approved Total (Overridden) (\$\$)		5,300.00		
(\$\$)	16,809.40	5,300.00	11,509.40	68.47
+ GST 7.00/7.00% (\$\$)	1,176.66	371.00	805.66	68.47
Nett Amount (\$\$)	17,986.06	5,671.00	12,315.06	68.47
+ Car Rental (3.0 x S\$140.00/day) (\$\$)		420.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		6,093.00		
Global Sum Settlement (\$\$)		6,090.00		

INSPECTION

Date of Assignment: 29/10/2020

Date Inspected: 29/10/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,485.10 F	*1,145.20 FL
2	1		*BOOTLID 2.0 EMBLEM	Necessary	62.00 F	*62.00 FL
3	1		*BOOTLID REAR LOGO	Necessary	86.60 F	*68.10 FL
4	1		*BOOTLID CAMRY EMBLEM	Necessary	88.50 F	*75.10 FL
5	2		*BOOTLID REFLECTORS	Not Necessary	1,110.20 F	*- FL
6	1		*BOOTLID OUTER GARNISH	Bent / Cracked	645.10 F	*485.10 FL
7	1		*BOOTLID INNER LOCK	Shorted	509.00 F	*399.50 FL
8	1		*BOOTLID INNER TRIM	Not Necessary	566.00 F	*- FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	399.10 F	*299.20 FL
10	1		*REAR BUMPER	Deformed	845.00 F	*622.10 FL
11	2		*REAR BUMPER RETAINERS	Not Necessary	130.20 F	*- FL
12	1		*REAR BUMPER REINFORCEMENT	Dented	599.00 F	*392.50 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	170.20 F	*- FL
15	1		*REAR END PANEL	Badly Dented	799.00 F	*625.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted / Torn	499.00 F	*315.20 FL
17	2		*TAILLAMPS	Cracked	1,690.20 F	*970.40 FL
18	2		*TAILLAMP HOUSING PANELS	Repair	970.20 F	*- FL
19	1		*REAR FLOOR PANEL	Repair	1,145.00 F	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD	Torn	620.00 F	*388.20 FL
21	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
22	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
23	1		*SET REAR REVERSE CAMERA	Serviceable	380.00 FS	*- FS
24	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,229.40	6,147.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,474.40
Total Parts (\$\$)	13,229.40	4,673.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	700.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,580.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >