

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011810/UVF3Q2

Date: 18/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30820919044
Claimant Vehicle No :	SGY6189K	Insured Vehicle No :	GBE3769X
Date of Loss:	28/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204092/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY6189K	Engine No:	1ZZ2964538
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100380666
Reg. Date:	02/10/2007 (Man. Year: 2007)	Odometer:	343608 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,027.54	2,473.06	1,554.48	38.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,600.00	820.00	33.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,447.54	4,073.06	2,374.48	36.83
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,447.54	3,200.00	3,247.54	50.37
+ GST 7.00/7.00% (S\$)	451.33	224.00	227.33	50.37
Nett Amount (S\$)	6,898.87	3,424.00	3,474.87	50.37

INSPECTION

Date of Assignment: 29/10/2020

Date Inspected: 09/11/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Nov 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY6189K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	1,272.40 FL	*1,272.40 FL
2	1		*TAILGATE DAMPER LH	Not Necessary	224.63 FL	*- FL
3	1		*TAILGATE DAMPER RH	Not Necessary	224.63 FL	*- FL
4	1		*TAILGATE EMBLEM	Necessary	76.80 FL	*76.80 FL
5	1		*TAILGATE OUTER HANDLE	Bent/Cracked	99.25 FL	*99.25 FL
6	1		*TAILGATE INNER LOCK	Dented/Jammed	470.40 FL	*470.40 FL
7	1		*TAILGATE WIPER MOTOR	Serviceable	699.60 FL	*- FL
8	1		*SET REAR NUMBER PLATE LAMP (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*END PANEL	Badly Dented	468.50 FL	*468.50 FL
10	1		*REAR BUMPER	Dented	550.30 FL	*485.10 FL
11	1		*REAR BUMPER RETAINER RH	Not Necessary	55.60 FL	*- FL
12	1		*REAR BUMPER RETAINER LH	Bent	55.60 FL	*55.60 FL
13	1		*REAR BUMPER REFLECTOR RH	Not Necessary	57.60 FL	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Not Necessary	57.60 FL	*- FL
15	2		*REAR BUMPER CLIP	Necessary	9.00 FL	*9.00 FL
16	1		*REAR BUMPER BRACKET LH	Dented	55.60 FL	*55.60 FL
17	1		*TAILLAMP LH	Serviceable	390.54 FL	*- FL
18	1		*REAR FENDER INNER SHIELD LH	Not Necessary	259.90 FL	*- FL
19	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
20	1		*REAR NUMBER PLATE }	Bent	30.00 FS	*40.00 FS
21	1		*REAR NUMBER PLATE HOLDER }	Bent	30.00 FS	*- FS
22	1		*REAR FENDER-LH (NPA)	Repair	0.00 FS	*- FS
23	1		*REAR END PANEL TOP GARNISH	Twisted	198.10 FL	*198.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,334.05	3,270.75
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,306.51	797.69
Total Parts (\$\$)	4,027.54	2,473.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,100.00	800.00
3	ANTI-RUST COATING	New	200.00	60.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
Gross Labour Cost (\$\$)			2,420.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >