

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011812/UGS3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : YN2940D	Insured Vehicle No :	SHA1142S
Date of Loss: 28/10/2020	Nature of Claim: TP	Claim No: MCT20100465

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN2940D		
Make & Model:	mitsubishi FE83BE6SRDEA, 3.0 D (A)	Engine No:	4M42A88927
Reg. Date:	05/01/2012 (Man. Year: 2011)	Chassis No:	FE83BEA20764
Colour:	White	Odometer:	285630 km
Engine Capacity:	2977 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16	Rear Tyre Size:	7.00 R16 (D)
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Double Coin 6/6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Double Coin 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,937.12	3,621.40	5,315.72	59.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,470.00	1,380.00	2,090.00	60.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,407.12	5,001.40	7,405.72	59.69
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	12,407.12	4,000.00	8,407.12	67.76
+ GST 7.00/7.00% (S\$)	868.50	280.00	588.50	67.76
Nett Amount (S\$)	13,275.62	4,280.00	8,995.62	67.76
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,607.45		

INSPECTION

Date of Assignment:	29/10/2020	
Date Inspected:	30/10/2020 Inspected At:	Automobile Integrated Management Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing) Singapore 415933
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Jan 2021)	
Parts:	N/A	MITSUBISHI FE83BE6SRDEA 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN2940D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,087.86 FL	*1,033.32 FL
2	1		*FRONT BUMPER BRACKET -RH	Not Necessary	241.55 FL	*- FL
3	1		*FRONT CORNER PANEL -RH	Not Necessary	251.62 FL	*- FL
4	1		*FRONT DOOR -RH	Distorted	1,827.61 FL	*1,827.61 FL
5	1		*FRONT DOOR WHEEL ARCH GARNISH	Not Necessary	210.52 FL	*- FL
6	1		*FRONT DOOR W/STRIP	Necessary	251.59 FL	*251.59 FL
7	1		*FRONT DOOR SEAL	Not Necessary	120.63 FL	*- FL
8	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	142.62 FL	*- FL
9	1		*FRONT DOOR GLASS RUN CHANNEL	Not Necessary	268.72 FL	*- FL
10	1		*FRONT DOOR INSULATION	Not Necessary	130.20 FL	*- FL
11	1		*FRONT DOOR CHECKER	Not Necessary	89.95 FL	*- FL
12	1		*FRONT DOOR HINGES	Lower Bent	393.50 FL	*125.20 FL
13	1		*FRONT DOOR PILLAR -RH -INNER	Repair	609.93 FL	*- FL
14	1		*FRONT DOOR PILLAR -RH -OUTER	Repair	1,407.60 FL	*- FL
15	1		*FRONT HEADLAMP -RH	Cracked	672.57 FL	*672.57 FL
16	1		*FRONT HEADLAMP SEAL	Torn	68.80 FL	*68.80 FL
17	1		*FRONT SIDE LAMP	Broken	242.65 FL	*242.65 FL
18	1		*FRONT SIGNAL LAMP	Cracked	310.23 FL	*310.23 FL
19	1		*FRONT STEP PANEL GARNISH	Cracked	296.56 FL	*296.56 FL
20	1		*BRAKE AIR CHAMBER	Not Necessary	410.25 FL	*- FL
21	1		*FRONT GRILLE ASSY	Repair	453.63 FL	*- FL
22	1		*FRONT WINDSCREEN RUBBER	Not Necessary	441.54 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	9,930.13	4,828.53
- List Item Discount on L Items 10.00/25.00% (\$\$)	993.01	1,207.13
Total Parts (\$\$)	8,937.12	3,621.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT ELECTRICAL WIRING	New	80.00	20.00
2	TO REMOVE ,REFIX FRONT WINDSCREEN	New	150.00	0.00
3	TO REMOVE ,REFIX DASHBOARD	New	300.00	0.00
4	TO REMOVE ,REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	0.00
5	TO RESPRAY UNDERCOATING	New	120.00	30.00
6	TO RESPRAY PAINTING AND ETC	New	1,200.00	750.00
7	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	1,500.00	580.00
			Gross Labour Cost (\$\$)	3,470.00
				1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >