



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8182U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER CENTRE GRILLE	BROKEN	114.00	114.00
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BONNET	DENTED	2,265.90	2,265.90
1	BONNET MOULDING	CUT	105.20	105.20
1	FRONT BUMPER CENTRE GRILLE TOP GARNISH	CRUSHED	80.00	80.00
	LESS 20% DISCOUNT		-727.86	-
	LESS 25% DISCOUNT		-	-909.83
			2,911.44	2,729.47
	<u>SPECIAL NETT ITEMS</u>			
1	EMBLEM SYOMBOL MARK (SN)	NECESSARY	28.70	28.70
			28.70	28.70
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	560.00
	SPRAY PAINTING.		500.00	400.00
	CHECK WIRING.		60.00	30.00
	TUFF KOTE.		50.00	30.00
			1,210.00	1,020.00
	GRAND TOTAL		4,150.14	3,778.17
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CS/SMO20011819/EUqf3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.