

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20011820/AVD3E2

**Date:** 03/03/2021

### REFERENCE

Insured/Claimant: TEO LIAN BENG Policy No: 2070112668  
Date of Loss: 25/10/2020 Nature of Claim: OD Claim No: 6918056878SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA6669J**  
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD893411  
Reg. Date: 30/07/2020 (Man. Year: 2020) Chassis No: WAUZZZF31L1101739  
Colour: Black Odometer: 5405 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$150,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	22,527.00	10,319.52	12,207.48	54.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,352.00	3,527.00	5,825.00	62.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>31,879.00</b>	<b>13,846.52</b>	<b>18,032.48</b>	<b>56.57</b>
<b>- Excess (S\$)</b>	400.00	400.00	0.00	0.00
<b>(S\$)</b>	31,479.00	13,446.52	18,032.48	57.28
<b>+ GST 7.00/7.00% (S\$)</b>	2,203.53	941.26	1,262.27	57.28
<b>Nett Amount (S\$)</b>	<b>33,682.53</b>	<b>14,387.78</b>	<b>19,294.75</b>	<b>57.28</b>

### INSPECTION

Date of Assignment: 30/10/2020  
Date Inspected: 29/10/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,615.00 FS	*2,091.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	410.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	58.00 FS	*- FS
4	1		*FRONT BUMPER TRIM	Not Necessary	352.00 FS	*- FS
5	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	215.00 FS	*- FS
6	2		*ULTRASOUND SENSOR SUPPORT - LH / RH	Not Necessary	50.00 FS	*- FS
7	1		*RADIATOR GRILLE INNER COVER	Not Necessary	51.00 FS	*- FS
8	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
9	1		*FRONT SPOILER	Cut	754.00 FS	*603.20 FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE TRIM - LH	Cut	162.00 FS	*129.20 FS
12	1		*FRONT BUMPER BRACKET	Not Necessary	21.00 FS	*- FS
13	1		*ULTRASOUND SENSOR BRACKET - LH	Not Necessary	25.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	1,907.00 FS	*1,525.60 FS
15	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	241.00 FS	*192.80 FS
16	1		*RADIATOR GRILLE COVER	Cracked	241.00 FS	*192.80 FS
17	1		*RADIATOR GRILLE BRACKET	Not Necessary	41.00 FS	*- FS
18	1		*FRONT BUMPER CARRIER	Not Necessary	834.00 FS	*- FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	101.00 FS	*- FS
20	1		*FRONT BUMPER TOP COVER	Cracked	121.00 FS	*96.80 FS
21	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
22	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
23	2		*FRONT PARKING AID SENSOR	Not Necessary	484.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
25	1		*SIGNAL HORN - LH HIGH TONE	Not Necessary	133.00 FS	*- FS
26	1		*SPRING SHACKLE - LH	Not Necessary	22.00 FS	*- FS
27	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	38.00 FS	*- FS
28	1		*FRONT FENDER - LH	Not Necessary	1,271.00 FS	*- FS
29	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	62.00 FS	*- FS
30	1		*FRONT FENDER BRACE - LH	Not Necessary	87.00 FS	*- FS
31	1		*FRONT FENDER BRACKET - LH	Not Necessary	31.00 FS	*- FS
32	1		*FRONNT WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
33	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
34	1		*BONNET	Repair	3,468.00 FS	*- FS
35	1		*BONNET ATTACHMENT PARTS	Not Necessary	293.00 FS	*- FS
36	2		*BONNET LID HINGE - LH / RH	Not Necessary	144.00 FS	*- FS
37	1		*BONNET IMPACT PROTECTION - CENTRE	Not Necessary	27.00 FS	*- FS
38	1		*BONNET RELEASE ELEMENT	Not Necessary	57.00 FS	*- FS
39	1		*BONNET RELEASE LEVER	Not Necessary	14.00 FS	*- FS
40	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
41	1		*HEADLIGHT MOUNTING - LH	Cracked	117.00 FS	*93.60 FS
42	1		*LED HEADLIGHT - LH	Cut	5,526.00 FS	*4,420.80 FS
43	1		*LIFT CULINDER - LH	Not Necessary	208.00 FS	*- FS
44	1		*LIFT CYLINDER HOSE	Not Necessary	79.00 FS	*- FS
45	1		*RADIATOR AIR GUIDE - LH	Cracked	37.00 FS	*29.44 FS
46	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	41.00 FS	*- FS
47	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,060.00 FS	*848.00 FS
48	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
49	1		*SUNDRIES	Necessary	300.00 FS	*19.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 22,527.00 10,319.52**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	550.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	New	4,800.00	1,775.00
5	TO CARRY OUT CALIBRATION FOR FRONT RADAR SENSOR	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (S\$)</b>	<b>9,352.00</b>
				<b>3,527.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >