

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 7258Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	R/H SIDE MIRROR	CUT	189.00	189.00
1	HANDLE BAR	NOT NECESSARY	306.00	-
1	FRONT FENDER	NOT NECESSARY	354.00	-
1	RADIATOR	NOT NECESSARY	1,542.00	-
1	R/H RADIATOR COVER	NOT NECESSARY	39.00	-
1	METER COVER	CRACKED	273.00	273.00
1	TANK BRA	NOT NECESSARY	612.00	-
1	TANK FUEL	NOT NECESSARY	2,184.00	-
1	R/H BAR END	NOT NECESSARY	117.00	-
1	R/H EXHAUST SLIDER	CUT	306.00	306.00
1	CRASH BAR R/H	BENT	804.00	250.00
1	RIDER FOOTPEGS R/H	NOT NECESSARY	126.00	-
1	PILLION FOOTPEGS R/H	NOT NECESSARY	126.00	-
1	R/H REAR SIDE COWLING	TO REPAIR SEE LABOUR	483.00	-
	LESS 10% DISCOUNT		-	-101.80
			7,461.00	916.20
	SPECIAL NETT ITEMS			
1	STEERING CONE & BEARING (SN)	NOT NECESSARY	120.00	-
1	FRONT FORK ALIGNMENT (SN)	NOT NECESSARY	220.00	-
1	EXHAUST (SN)	DENTED / BENT	4,044.00	1,500.00
1	BOX (SN)	CRACKED	450.00	200.00
			4,834.00	1,700.00
	<u>LABOUR</u>			
	WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	FRAME ALIGNMENT.	NOT NECESSARY	200.00	-
	WORKMANSHIP TO RENEW DAMAGE PARTS & AREAS. INCLUSIVE OF THE REPAIR OF R/H REAR SIDE COWLING.		350.00	200.00
			670.00	200.00
	GRAND TOTAL		12,965.00	2,816.20

Report Ref No. CS/GAI20011825/Uvf3e2





RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		,

Report Ref No. CS/GAI20011825/Uvf3e2

CHUA KANG SENG
Licensed Appraiser