

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20011830/KVF3E2

Date: 01/04/2021

REFERENCE

Insured/Claimant:	PETS DAY OUT	Policy No:	2070017071	Claim No:	7248572269SG
Date of Loss:	19/10/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ8868R	Engine No:	198A30007662572
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 (M)	Chassis No:	ZFA26300006C73623
Reg. Date:	31/08/2016 (Man. Year: 2016)	Odometer:	75476 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 2 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,828.47	17,390.27	4,438.20	20.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	3,740.00	1,580.00	29.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,148.47	21,130.27	6,018.20	22.17
Approved Total (Overridden) (S\$)		13,800.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	26,348.47	13,000.00	13,348.47	50.66
+ GST 7.00/7.00% (S\$)	1,844.39	910.00	934.39	50.66
Nett Amount (S\$)	28,192.86	13,910.00	14,282.86	50.66

INSPECTION

Date of Assignment:	30/10/2020	BCC Automotive Pte Ltd (Sin Ming)
Date Inspected:	30/10/2020 Inspected At:	Blk 1 Sin Ming Industrial Estate, Sector C #01-101
Estimated Period of Repair:	9.0 days	Singapore 575636

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cracked	612.00 FL	*612.00 FL
2	1	*FRONT BUMPER LOWER GRILLE	Serviceable	450.00 FL	*- FL
3	1	*FRONT BUMPER BRACKET CENTER	Serviceable	98.00 FL	*- FL
4	1	*FRONT BUMPER BRACKET LH	Distorted	98.00 FL	*98.00 FL
5	1	*FRONT BUMPER TOW COVER	Serviceable	45.00 FL	*- FL
6	1	*FRONT BUMPER FOG LIGHT BRACKET LH	Repair	65.00 FL	*- FL
7	1	*FRONT BUMPER FOG LIGHT BRACKET RH	Serviceable	65.00 FL	*- FL
8	1	*FRONT BUMPER UNDER TRAY CENTER SUPPORT	Serviceable	162.00 FL	*- FL
9	1	*FRONT BUMPER REINFORCEMENT	Repair	405.00 FL	*- FL
10	1	*FRONT BUMPER REINFORCEMENT SPONGE	Serviceable	127.00 FL	*- FL
11	1	*FRONT BUMPER REINFORCEMENT SPONGE SUPPORT	Serviceable	255.00 FL	*- FL
12	1	*FRONT BUMPER GRILLE	Dented	420.00 FL	*420.00 FL
13	1	*FRONT BUMPER GRILLE FIAT BADGE	Necessary	155.00 FL	*155.00 FL
14	1	*FRONT BUMPER CENTRE SUPPORT	Serviceable	105.00 FL	*- FL
15	1	*FRONT END TOP PANEL SUPPORT CENTRE	Buckled	280.00 FL	*280.00 FL
16	1	*FRONT END TOP PANEL SUPPORT LH	Bent	155.00 FL	*155.00 FL
17	1	*FRONT END TOP PANEL SUPPORT BRACKET LH	Bent	76.00 FL	*76.00 FL
18	1	*FRONT LEFT WHEEL ARCH	Distorted	205.00 FL	*205.00 FL
19	1	*FRONT LH FENDER PANEL	Bent	320.00 FL	*320.00 FL
20	1	*FRONT RH FENDER PANEL	Bent	320.00 FL	*320.00 FL
21	1	*FRONT LH FENDER PANEL BRACKET	Bent	85.00 FL	*85.00 FL
22	1	*FRONT RH FENDER PANEL BRACKET	Repair	85.00 FL	*- FL
23	1	*FRONT BONNET	Bent	660.00 FL	*660.00 FL
24	1	*FRONT BONNET LOCK	Repair	185.00 FL	*- FL
25	1	*FRONT LH HEADLAMP	Broken	550.00 FL	*550.00 FL
26	1	*COOLANT TANK	Serviceable	175.00 FL	*- FL
27	1	*RADIATOR	Serviceable	350.00 FL	*- FL
28	1	*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
29	1	*ABS PUMP (Supplementary)	Dented	3,682.52 FL	*3,682.52 FL
30	1	*ABS BRACKET (Supplementary)	Bent	320.00 FL	*320.00 FL
31	2	*ABS METAL PIPE 1 & 2 (Supplementary)	Dented	608.00 FL	*608.00 FL
32	1	*ABS METAL PIPE 3 (Supplementary)	Dented	285.00 FL	*285.00 FL
33	2	*ABS METAL PIPE 4 & 5 (Supplementary)	Dented	700.00 FL	*700.00 FL
34	1	*ABS METAL PIPE 6 (Supplementary)	Dented	405.00 FL	*405.00 FL
35	1	*FUEL BOX WITH WIRE HARNESS (Supplementary)	Cracked	4,500.00 FL	*4,500.00 FL
36	1	*FUEL BOX SUPPORT (Supplementary)	Cracked	55.00 FL	*55.00 FL
37	1	*FUSE BOX PROTECTION COVER (Supplementary)	Cracked	45.00 FL	*45.00 FL
38	1	*RH FENDER UPPER GARNISH (Supplementary)	Mtg Cracked	280.00 FL	*280.00 FL
39	1	*LH FENDER UPPER GARNISH (Supplementary)	Missing	280.00 FL	*280.00 FL
40	1	*FRONT LH STRUT COMPLETE (Supplementary)	Bent	1,970.00 FL	*1,970.00 FL
41	1	*WIPER PANEL (Supplementary)	Dented	208.00 FL	*208.00 FL
42	1	*RADIATOR TOP PANEL (Supplementary)	Buckled	380.00 FL	*380.00 FL
43	1	*FRONT LH PILLAR (Supplementary)	Repair	720.00 FL	*- FL
44	1	*FRONT BONNET LH HINGES (Supplementary)	Distorted	125.00 FL	*125.00 FL

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT BONNET RH HINGES (Supplementary)	Distorted	125.00 FL	*125.00 FL
46	1	*FRONT HEADLAMP SUPPORT BRACKET (Supplementary)	Missing	180.00 FL	*180.00 FL
47	1	*RADIATOR GRILLE (Supplementary)	Cracked	428.00 FL	*428.00 FL
48	1	*FRONT LH HEADLAMP SUPPORT BRACKET (Supplementary)	No such part	98.00 FL	*- FL
49	2	*FRONT BUMPER LOWER GRILLE LH & RH SUPPORT BRACKET (Supplementary)	Repeated	220.00 FL	*- FL
50	1	*FRONT BUMPER LOWER GRILLE CENTER SUPPORT BRACKET (Supplementary)	Repair	108.00 FL	*- FL
51	1	*FRONT BUMPER FOG LIGHT LH SUPPORT BRACKET (Supplementary)	Repair	85.00 FL	*- FL
52	1	*MODULE HOLDER (Supplementary)	Repair	250.00 FL	*- FL
53	1	*RADIATOR TOP SEAL GASKET (Supplementary)	Serviceable	65.00 FL	*- FL
54	1	*BONNET STAND (Supplementary)	Missing	455.00 FL	*455.00 FL
55	1	*BONNET STAND CLIPS (Supplementary)	Missing	50.00 FL	*50.00 FL
56	1	*BONNET CABLE (Supplementary)	Jammed	255.00 FL	*255.00 FL
57	1	*HORN (Supplementary)	Serviceable	300.00 FL	*- FL
58	1	*FRONT LH SHOCK ABSORBER (Supplementary)	Serviceable	380.00 FL	*- FL
59	5	*FRONT WHEELS ARCH CLIPS (Supplementary)	Necessary	50.00 FL	*50.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,240.52	19,322.52
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,412.05	1,932.25
Total Parts (\$\$)	21,828.47	17,390.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY THE AFFECTED AREA	New	1,500.00	1,200.00
2	TO PANEL BEAT THE AFFECTED AREA	New	1,200.00	1,000.00
3	COMPUTERIZE FOUR WHEELS ALIGNMENT	New	150.00	60.00
4	TO REPLACE RADIATOR, COOLANT TANK, COOLING SYSTEM AND TOP UP GAS	New	300.00	150.00
5	TO PANEL BEAT AND STRAIGHTEN FRONT CHASSIS AND FRAME PORTION	New	950.00	900.00
6	TOWING CHARGE (Supplementary)	New	120.00	80.00
7	ABS PROGRAMMING (Supplementary)	New	300.00	150.00
8	LABOUR TO REPAIR RADIATOR, ABS PUMP, FUSE BOX AND ABSORBER INCLUDING WIRE HARNESS (Supplementary)	New	800.00	200.00
Gross Labour Cost (\$\$)			5,320.00	3,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >