

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG20011833/UTF3Q2

**Date:** 26/11/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000886177

**Claimant**  
**Vehicle No :** SKQ8290G

**Insured Vehicle No :** SLK7885S

Date of Loss: 25/10/2020

Nature of Claim: TP

Claim No: 249156

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKQ8290G**

Make & Model: VOLVO XC60, 2.0 T5 (A)

Engine No: B4204T111075075

Reg. Date: 29/12/2014 (Man. Year: 2014)

Chassis No: YV1DZ40LDF2649661

Colour: Brown

Odometer: 155405 km

Engine Capacity: 1969 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/60R18

Rear Tyre Size:

235/60R18

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	36,936.93	8,865.14	28,071.79	76.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,470.00	2,790.00	4,680.00	62.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>44,406.93</b>	<b>11,655.14</b>	<b>32,751.79</b>	<b>73.75</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,300.00</b>		
<b>(S\$)</b>	44,406.93	9,300.00	35,106.93	79.06
<b>+ GST 7.00/7.00% (S\$)</b>	3,108.49	651.00	2,457.49	79.06
<b>Nett Amount (S\$)</b>	<b>47,515.42</b>	<b>9,951.00</b>	<b>37,564.42</b>	<b>79.06</b>

### INSPECTION

Date of Assignment: 30/10/2020

Date Inspected: 02/11/2020 Inspected At:

Kaizen Motors Pte Ltd (HQ)

68 KAKI BUKIT AVE 6, #02-12 ARK

@ KAKI BUKIT

Singapore 417896

Estimated Period of Repair: 8.0 days

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2020)
<b>Parts:</b>	M1-SUV	VOLVO XC60 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKQ8290G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE ASSY	Repair	3,782.30 F	*- FL
2	1	*TAILGATE WINDSCREEN	Not Necessary	1,711.80 F	*- FL
3	1	*TAILGATE EMBLEM (VOLVO)	Necessary	136.80 F	*100.44 FL
4	1	*TAILGATE EMBLEM (XC60)	Necessary	160.10 F	*115.11 FL
5	1	*TAILGATE EMBLEM (T5)	Necessary	136.80 F	*92.07 FL
6	1	*TAILGATE OUTER CHROME GARNISH	Not Necessary	531.80 F	*- FL
7	2	*TAILGATE NO PLATE LAMP	Not Necessary	626.40 F	*- FL
8	1	*TAILGATE NO PLATE LAMP GARNISH	Not Necessary	554.70 F	*- FL
9	1	*TAILGATE INNER LOCK	Not Necessary	652.70 F	*- FL
10	1	*TAILGATE LOCK CATCH	Not Necessary	56.00 F	*- FL
11	1	*TAILGATE WEATHERSTRIPE	Twisted	270.80 F	*215.23 FL
12	1	*TAILGATE INNER TRIM	Not Necessary	746.10 F	*- FL
13	2	*TAILGATE HINGE	Not Necessary	1,045.20 F	*- FL
14	2	*TAILGATE ABSORBER	Not Necessary	2,202.20 F	*- FL
15	2	*TAIL LAMP ASSY	Not Necessary	1,949.60 F	*- FL
16	2	*TAIL LAMP INNER SEALER	Not Necessary	140.20 F	*- FL
17	2	*TAIL LAMP BOTTOM CORNER COVER	Not Necessary	1,100.60 F	*- FL
18	1	*REAR BUMPER ASSY	Distorted	2,974.10 F	*1,897.33 FL
19	1	*REAR BUMPER ASSY GARNISH TOP	Distorted	556.30 F	*538.92 FL
20	2	*REAR BUMPER SIDE RETAINER	Not Necessary	252.80 F	*- FL
21	1	*REAR BUMPER TOWING COVER	Not Necessary	96.70 F	*- FL
22	1	*REAR BUMPER LIP	Distorted	1,348.60 F	*1,336.59 FL
23	2	*REAR BUMPER REFLECTOR	Not Necessary	262.00 F	*- FL
24	1	*REAR BUMPER UNDER COVER	Distorted	853.40 F	*255.00 FL
25	1	*END PANEL OUTER	Badly Dented	1,803.90 F	*902.20 FL
26	1	*END PANEL INNER	Repair	537.80 F	*- FL
27	1	*END PANEL TOP TRIM	Not Necessary	359.30 F	*- FL
28	1	*REAR FLOOR PANEL	Crumpled/Buckled	899.60 F	*899.60 FL
29	1	*REAR FLOOR PANEL TOP BOARD	Not Necessary	577.10 F	*- FL
30	1	*TAIL GATE WINDSCREEN MOULDING	Not Necessary	325.00 F	*- FL
31	1	*TAIL GATE WINDSCREEN INNER SEAL	Not Necessary	273.00 F	*- FL
32	1	*REAR WINDSCREEN SEALANT	Not Necessary	276.00 F	*- FL
33	1	*REVERSE CAMERA	Not Necessary	890.50 F	*- FL
34	1	*REVERSE SENSOR (4 Pcs)	Shorted (2 Pcs only)	1,840.00 F	*523.98 FL
35	1	*REAR NO PLATE WITH COVER	Not Necessary	80.00 F	*- FL
36	1	*REAR EXHAUST ASSY	Repair	3,155.50 F	*- FL
37	2	*REAR EXHAUST TIP	Bent	526.00 F	*391.76 FL
38	2	*REAR EXHAUST TIP GARNISH	Cracked	747.00 F	*290.00 FL
39	1	*REAR BUMPER REINFORCEMENT	Dented/Bent	1,066.00 F	*1,066.00 FL
40	1	*REAR EXHAUST HEATSHIELD	Bent	530.37 F	*530.37 FL
41	1	*REAR END PANEL TOP RETAINER	Cracked	71.86 F	*71.86 FL
42	20	*END PANEL TOP TRIM CLIP	Not Necessary	160.00 F	*- FL
43	10	*TAIL GATE OUTER CHROME GARNISH CLIP	Not Necessary	80.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	10		*TAILGATE INNER TRIM CLIP	Not Necessary	80.00 F	*- FL
45	10		*TAIL LAMP CLIP	Not Necessary	100.00 F	*- FL
46	1		*BODY PANEL JOINT SEALANT	Necessary	250.00 FS	*50.00 FS
47	20		*REAR BUMPER CLIP	Necessary	160.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>36,936.93</b>	<b>9,326.46</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$)</b>	0.00	461.32
<b>Total Parts (\$)</b>	<b>36,936.93</b>	<b>8,865.14</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR CHECKING ON WIRING	New	120.00	30.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF END PANEL INNER,TAIL GATE,TAIL LAMP,BUMPER ASSY,REVERSE SENSOR,REVERSE CAMERA	New	3,200.00	1,400.00
3	TRANSFERRING OF TAIL GATE,WIPER ARM,EMBLEMS,SPOILER,INNER BACK BOARD TRIMMING TO NEW TAIL GATE	New	950.00	80.00
4	TRANSFERRING OF REAR WINDSCREEN	New	450.00	120.00
5	SPRAYPAINTING	New	2,250.00	1,100.00
6	APPLYING OF RUST-PROOFING	New	250.00	60.00
7	LABOUR FOR RETROFITITNG MOULDING & WEATHERSTRIP	New	250.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,470.00</b>	<b>2,790.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >