



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6698Y

| Qty                                | Description of Parts  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |   |               |                           |                   |
| 1                                  | FRONT BUMPER (CONSISTENT)   | TORN          | 695.80                    | 695.80            |
| 1                                  | FRONT BUMPER FOGLAMP RH (CONSISTENT)  | NOT NECESSARY | 206.00                    | -                 |
| 1                                  | FRONT BUMPER FOGLAMP HOUSING C/W COVER GARNISH RH (CONSISTENT)                                | CUT           | 106.00                    | 106.00            |
| 1                                  | FRONT BUMPER LOWER GRILLE (CONSISTENT)  | NOT NECESSARY | 169.00                    | -                 |
| 2                                  | FRONT BUMPER SIDE RETAINER @\$19.00 (CONSISTENT)  | NECESSARY     | 38.00                     | 38.00             |
| 1                                  | FRONT GRILLE LOGO (CONSISTENT)  | NOT NECESSARY | 51.00                     | -                 |
| 1                                  | FRONT GRILLE WITH CHROME (CONSISTENT)   | NOT NECESSARY | 420.00                    | -                 |
| 1                                  | HEAD LAMP RH (CONSISTENT)   | CRACKED       | 1,558.00                  | 1,558.00          |
| 1                                  | HEAD LAMP LOWER BRACKET RH (CONSISTENT)   | CRACKED       | 18.00                     | 18.00             |
| 1                                  | FRONT FENDER COWLING RH (CONSISTENT)  | NOT NECESSARY | 89.00                     | -                 |
|                                    | LESS 10% DISCOUNT   |               | -335.08                   | -241.58           |
|                                    |   |               | 3,015.72                  | 2,174.22          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |   |               |                           |                   |
| 1                                  | SET FRONT BUMPER CLIP (SN) (CONSISTENT)   | NECESSARY     | 80.00                     | 30.00             |
| 1                                  | SET FRONT FENDER COWLING CLIP (SN) (CONSISTENT)   | NOT NECESSARY | 80.00                     | -                 |
| 1                                  | SET FRONT GRILLE CLIP (SN) (CONSISTENT)   | NOT NECESSARY | 60.00                     | -                 |
|                                    |   |               | 220.00                    | 30.00             |
| <b><u>LABOUR</u></b>               |   |               |                           |                   |
|                                    | PANEL BEATING,REMOVAL AND REPLACING PARTS.  |               | 600.00                    | 300.00            |
|                                    | TO SPRAY PAINT AFFECTED AREA.   |               | 600.00                    | 200.00            |
|                                    | TUFF COAT.  | NOT NECESSARY | 150.00                    | -                 |
|                                    | WIRING CHECK.   |               | 180.00                    | 30.00             |
|                                    | REFOCUS HEADLAMP BEAM.  | NOT NECESSARY | 60.00                     | -                 |
|                                    | REMOVE AND REFIX BUMPER SENSOR.   |               | 80.00                     | 50.00             |
|                                    | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC. | NOT NECESSARY | 250.00                    | -                 |
|                                    |   |               | 1,920.00                  | 580.00            |
| <b>GRAND TOTAL</b>                 |   |               | <b>5,155.72</b>           | <b>2,784.22</b>   |



|   |  |  |                 |
|---|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>2,200.00</b> |
|---|--|--|-----------------|

Report Ref No. CC4/ASM20011841/Aba3q2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**