

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011849/QPA3Q2
Date: 29/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100349979
Claimant Vehicle No :	CB6468Z	Insured Vehicle No :	SKK7236C
Date of Loss:	23/10/2020	Nature of Claim:	TP
		Claim No:	5819049800SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB6468Z		
Make & Model:	MITSUBISHI ROSA, 4.9 D BE63DGRMDA MT 2WD (M)	Engine No:	4M50D20656
Reg. Date:	03/12/2009 (Man. Year: 2008)	Chassis No:	BE63DGF00116
Colour:	White	Odometer:	349666 km
Engine Capacity:	4899 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/75 R17	Rear Tyre Size:	205/75 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,589.37	86.40	6,502.97	98.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,800.00	880.00	3,920.00	81.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	11,389.37	966.40	10,422.97	91.51
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		

Nett Liability (S\$)	1,453.85
Global Sum Settlement (S\$)	1,450.00

INSPECTION

Date of Assignment: 30/10/2020

Date Inspected: 05/11/2020

Estimated Period of Repair: 3.0 days

Inspected At:

A T AUTO CONSULTANT
113 TECK WHYE LANE, #05-650, SINGAPORE 680113

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR SIDE WHEEL ARCH PANEL	Repair	3,685.10 FL	*- FL
2	1		*REAR SIDE WHEEL ARCH PANEL SIGNAL LAMP RH	Scratched	115.20 FL	*115.20 FL
3	1		*REAR WHEEL ARCH MUD FLAP	Serviceable	113.40 FL	*- FL
4	1		*REAR BUMPER	Repair	2,785.60 FL	*- FL
5	2		*WINDSCREEN SEALANT X2 GLASS PANELS	Not Necessary	560.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	7,259.30 115.20
					- List Item Discount on L Items 10.00/25.00% (\$)	669.93 28.80
					Total Parts (\$)	6,589.37 86.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,600.00	400.00
2	SPRAY PAINTING ON AFFECTED AREA	New	1,200.00	400.00
3	WIRING CHARGES & TESTING COMMISSIONING	New	200.00	30.00
4	APPLY PUTTY AND ANTI-CORROSIO TO AFFECTED PARTS	New	200.00	50.00
5	R/R REAR ROW PASSENGER CHAIR X2 TO FACILITATE HOT WORK	New	500.00	0.00
6	R/R REAR SIDE INNER TRIM TO FACILITATE HOT WORK	New	500.00	0.00
7	R/R REAR SIDE PANEL TOP WINDSCREEN	New	600.00	0.00
Gross Labour Cost (S\$)			4,800.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >