6/16/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Date: 16/06/2021

Engine No:

Chassis No:

Odometer:

Our File No:

REFERENCE

Date of Loss:

Insured/Claimant: SING FU SENG BUILDING CONSTRUCTION PTE LTD

26/10/2020

Policy No: DMCVSNW00065582000

Nature of Claim: OD

Claim No: SNM20D204063/C04/CHUAKK

1KD2702200

112066 km

KDY2318029044

CS/CTI20011855/KVD3Q2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG6689M

Make & Model: TOYOTA DYNA, 3.0 D (M)
Req. Date: 27/09/2017 (Man. Year: 2017)

Colour: White
Engine Capacity: 2982 cc
Market Value/New Car Price: \$\$51,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R15X8 (D)

Front Left Side: Michelin 6 mm Rear Left Side: GREEN-MAX 2/2 mm Front Right Side: Michelin 6 mm Rear Right Side: GREEN-MAX 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,952.00	5,387.60	1,564.40	22.50
Miscellaneous Items	75.00	75.00	0.00	0.00
Labour	3,305.40	3,137.40	168.00	5.08
Paintwork Labour	1,433.49	1,413.20	20.29	1.42
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,765.89	10,013.20	1,752.69	14.90
- Excess (S\$)	350.00	350.00	0.00	0.00
(S\$)	11,415.89	9,663.20	1,752.69	15.35

Nett Amount (S\$)	12,215.00	10,339.62	1,875.38	15.35
+ GST 7.00/7.00% (S\$)	799.11	676.42	122.69	15.35

INSPECTION

Date of Assignment: 30/10/2020 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)

Date Inspected: 30/10/2020 Inspected At: 160 Sin Ming Drive #04-01, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 16.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Jun 2021)

Parts: N/A TOYOTA DYNA 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG6689M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*Spare Parts		6,952.00 F	*5,387.60 F
i –i faliolise part.		Total Parts (S\$)	6,952.00	5,387.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars	Repairer's	Amount
Miscellaneous Items		
1 1 Extra	75.00	75.00
Sub Total (S\$)	75.00	75.00

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 Total Paint Including Material	New	1,433.49	1,413.20
<u>Labour Items</u>			
2 Total of Labour	New	3,305.40	3,137.40
	Gross Labour Cost (S\$)	4,738.89	4,550.60

Report was unsubmitted during this print-out.

< END OF ESTIMATES >