

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011857/KEA3Q2**Date:** 17/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLR532U	Insured Vehicle No :	SHA4023H
Date of Loss:	30/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100485

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR532U	Engine No:	LEB5948881
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31248864
Reg. Date:	28/07/2017 (Man. Year: 2017)	Odometer:	189099 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,506.64	3,978.16	528.48	11.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,900.00	2,660.00	240.00	8.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,406.64	6,638.16	768.48	10.38
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	7,406.64	5,300.00	2,106.64	28.44
+ GST 7.00/7.00% (S\$)	518.46	371.00	147.46	28.44
Nett Amount (S\$)	7,925.10	5,671.00	2,254.10	28.44
+ Loss of Use (10.0 x S\$60.00/day) (S\$)		600.00		
Nett Liability (S\$)		6,271.00		

INSPECTION

Date of Assignment:	30/10/2020	Cheng Hoe Motor Pte Ltd (AMK)
Date Inspected:	30/10/2020 Inspected At:	10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT
Estimated Period of Repair:	8.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR532U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Bent	798.10 FL	*798.10 FL
2	5	*REAR BUMPER CLIP	Necessary	19.00 FL	*19.00 FL
3	1	*REAR TAILGATE	Bent	997.70 FL	*997.70 FL
4	1	*TAILGATE INNER LOCK	Dented	96.70 FL	*96.70 FL
5	1	*TAILGATE INNER RUBBER	Cut	101.40 FL	*101.40 FL
6	1	*TAILGATE EMBLEM HYBRID	Necessary	66.30 FL	*66.30 FL
7	1	*TAILGATE EMBLEM VEZEL	Necessary	43.00 FL	*43.00 FL
8	1	*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	109.30 FL	*109.30 FL
9	1	*REAR END PANEL	Bent	411.90 FL	*411.90 FL
10	1	*REAR END PANEL INNER TOP GARNISH	Mtg Distorted	80.60 FL	*80.60 FL
11	1	*REAR END PANEL BUZZER SENSOR	Necessary	85.00 FL	*85.00 FL
12	1	*REAR END PANEL ANTENNA	Not Necessary	58.10 FL	*- FL
13	1	*REAR LUGGAGE COMPARTMENT PANEL	Cracked	787.50 FL	*787.50 FL
14	1	*REAR LUGGAGE COMPARTMENT TOP BOARD	Dented	430.30 FL	*430.30 FL
15	1	*REAR LUGGAGE TOOL BOX	Dented	137.30 FL	*137.30 FL
16	1	*REAR LUGGAGE COMPARTMENT PANEL LOWER UNDER COVER	Buckled	190.00 FL	*190.00 FL
17	1	*REAR EXHAUST MUFFLER	Repair	552.50 FL	*- FL
18	1	*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
19	1	*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
20	1	*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS
21	1	*REAR LUGGAGE COMPARTMENT PANEL TOP COAT	Necessary	100.00 FS	*60.00 FS
22	1	*TAILGATE OUTER GARNISH	Cracked	193.60 FL	*193.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 5,538.30 4,887.70
- List Item Discount on L Items 20.00/20.00% (\$\$) 1,031.66 909.54

Total Parts (\$\$) 4,506.64 3,978.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER & ATTACHMENTS TAILGATE SPOILER & ATTACHMENTS TAILLAMPS TO CUT ,WELD & RENEW REAR END PANEL,REAR LUGGAGE PANEL KNOCKING & REPAIR REAR CHASSIS FRAME & REALIGN THE SAME	New	1,200.00	1,200.00
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REAR END PANEL REAR LUGGAGE PANEL ,REAR CHASSIS FRAME & ALL AFFECTED AREAS	New	1,000.00	900.00
4	REMOVE & REFIX REAR FENDER GARNISH ,SEAT TO FACILITATE REPAIR	New	150.00	100.00
5	REMOVE & REFIX REAR MUFFLER & REALIGN THE SAME	New	80.00	60.00
6	RUSTPROOFING	New	90.00	60.00
7	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	60.00	60.00
8	REMOVE & REFIX HYBRID BATTERY AND RESET SYSTEM	New	200.00	160.00
Gross Labour Cost (\$\$)			2,900.00	2,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >