LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20011861/ASD3E2

Date: 18/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100506373

Claimant Vehicle

CM 161257

No: SMJ6135Z Insured Vehicle No: SLM5278Y

Date of Loss: 28/10/2020 Nature of Claim: TP Claim No: 7424684954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ6135Z

 Make & Model:
 TOYOTA C-HR HYBRID, 1.8 S CVT (A)
 Engine No:
 2ZR2B45642

 Reg. Date:
 13/03/2019 (Man. Year: 2018)
 Chassis No:
 ZYX102142660

 Colour:
 Silver
 Odometer:
 156139 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,896.80	1,886.40	3,010.40	61.48
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,900.00	730.00	1,170.00	61.58
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,796.80	2,616.40	4,180.40	61.51
	Approved Total (Overridden) (S\$)		2,100.00		
	Nett Amount (S\$)	6,796.80	2,100.00	4,696.80	69.10

INSPECTION

Date of Assignment: 30/10/2020

Flying High Spray Painting (HQ)

Date Inspected: 02/11/2020 Inspected At: BLK 1 Kaki Bukit Ave 6, #01-29 Auto Bay

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Hiew May Fung

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,030.00 F	*1,030.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	124.60 F	*- FL
4	2		*REAR BUMPER SIDE GARNISH	Not Necessary	185.40 F	*- FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	124.60 F	*- FL
6	1		*REAR BUMPER TOW COVER	Deformed	32.70 F	*32.70 FL
7	1		*REAR BUMPER LOWER GARNISH	Deformed	620.00 F	*620.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Bent	482.50 F	*482.50 FL
9	1		*REAR END PANEL	Repair	689.30 F	*- FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	295.50 F	*- FL
11	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
12	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
13	1		*TAILGATE OUTER GARNISH	Repair	882.20 F	*- FL
14	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*-FS
15	1		*OSAKA TOYOPET EMBLEM	Necessary	40.00 FS	*40.00 FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.			
				Sub Total (S\$)	4,896.80	2,435.20
			- List Item Discount	on L Items 0.00/25.00% (S\$)	0.00	548.80
				Total Parts (S\$)	4,896.80	1,886.40
			Report was unsubmitted	I during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			,
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	800.00	350.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
		Gross Labour Cost (S\$)	1,900.00	730.00
	Report	was unsubmitted during this print-out.		

< END OF ESTIMATES >