

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011871/KRS3Q2

Date: 15/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : GBB1900L

Insured Vehicle No : GU5144S

Date of Loss: 28/10/2020

Nature of Claim: TP

Claim No: 7281540914SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB1900L**

Make & Model: HYUNDAI H-1 STAREX, 2.5 D CRDi (A)

Engine No: D4CB8404674

Reg. Date: 05/09/2008 (Man. Year: 2008)

Chassis No: KMFWBH7JR9U094350

Colour: Silver

Odometer: 195236 km

Engine Capacity: 2497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Maxmiler 9 mm

Rear Left Side: West Lake 7 mm

Front Right Side: Maxmiler 9 mm

Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,894.40	2,214.40	680.00	23.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,210.00	1,130.00	48.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,234.40	3,424.40	1,810.00	34.58
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	5,234.40	2,750.00	2,484.40	47.46
+ GST 7.00/7.00% (S\$)	366.41	192.50	173.91	47.46
Nett Amount (S\$)	5,600.81	2,942.50	2,658.31	47.46
+ Loss of Use (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,664.50		
Global Sum Settlement (S\$)		3,600.00		

INSPECTION

Date of Assignment: 30/10/2020

Date Inspected: 02/11/2020

Inspected At:

World Auto Pte Ltd (HQ)

No.5, Kim Chuan Lane

Singapore 537070

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	980.00 FL	*980.00 FL
2	1		*REAR TAILGATE INNER LOCK	Dented	110.00 FL	*110.00 FL
3	1		*REAR BUMPER	Buckled	450.00 FL	*450.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	420.00 FL	*420.00 FL
5	1		*REAR END PANEL	Repair	380.00 FL	*- FL
6	1		*REAR END PANEL TOP GARNISH	Cracked	95.00 FL	*95.00 FL
7	1		*REAR BOOT WEATHER STRIP (50%)	Distorted / Dented	88.00 FS	*55.00 FS
8	1		*REAR TAIL LAMP -RH (CRACKED)	Not Consistent With The Impact	260.00 FL	*- FL
9	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
11	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
12	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
13	1		*SET REVERSE SENSOR	Dented	280.00 FS	*200.00 FS
14	1		*SET REAR NUMBER PLATE W/CASING	Dented	60.00 FS	*45.00 FS
15	1		*REAR BUMPER INNER FOAM	Cracked	110.00 FL	*110.00 FL
16	1		*REAR BUMPER TOP GARNISH	Dented	78.00 FL	*78.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,471.00	2,663.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	576.60	448.60

Total Parts (\$\$)	2,894.40	2,214.40
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	WIRING CHECK AND RECTIFT WHERE NECESSARY INCLUDING DRILL HOLES ON NEW REAR BUMPER FOR INSTALLATION OF NEW SET OF REVERSE SENSORS	New	180.00	50.00
3	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
4	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,CUT /WELD REAR END PANEL,STRAIGHTEN REAR CHASSIS WHERE NECESSAR AND REPLACE ABOVE PARTS	New	1,200.00	500.00
5	PUTTY AND SPRAY PAINT REAR ACCIDENT AFFECTED AREAS (INNER/OUTER)	New	600.00	480.00
Gross Labour Cost (\$\$)			2,340.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >