



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102377

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 09/04/2021
Reference CC6/FCI20011887/Krs3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLN 9527Y
Insured Veh. SHA 771H
Claim No. D20004454MFSH
Policy No. D-18088937MFSH
Accident Date 30/10/2020
Inspection Date 24/11/2020

Description	Total
Survey Inspection	273.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	273.00
GST (7%)	19.11
Grand Total	292.11

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI20011887/Krs3q2 Date: 09/04/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 771H	Veh. Inspected	SLN 9527Y	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D20004454MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	24/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6GL1071H0107340	Colour	METALLIC BLUE	
Odometer	79594 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	PIRELLI	8 mm	
L/H Front Tyre	225/55 R17	PIRELLI	8 mm	
R/H Rear Tyre	225/55 R17	PIRELLI	8 mm	
L/H Rear Tyre	225/55 R17	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2020	Inspection Date	24/11/2020	
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 9527Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP/RH	CUT	1,950.00	1,950.00
2	FRONT HEADLAMP BRACKET/RH @\$112.00	SERVICEABLE	224.00	-
1	FRONT BUMPER	BENT	895.90	895.90
2	FRONT BUMPER RETAINER @\$89.60	O/S DISTORTED	179.20	89.60
1	FRONT BUMPER SIDE MLDG	DENTED	119.60	119.60
1	FRONT BUMPER LOWER GRILLE/CENTRE	SERVICEABLE	198.20	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	566.50	-
1	FRONT GRILLE	CRACKED	425.30	425.30
2	FRONT GRILLE CHROME LOWER @\$112.00	O/S CRACKED	224.00	112.00
8	FRONT GRILLE CLIPS @\$3.00	NECESSARY	24.00	24.00
1	FRONT GRILLE EMBLEM	NECESSARY	128.70	128.70
1	FRONT RADIATOR TOP PANEL	BUCKLED	319.60	319.60
1	FRONT WIPER TANK	SERVICEABLE	89.60	-
1	FRONT FOGLAMP COVER/RH	SERVICEABLE	89.90	-
	LESS 10% DISCOUNT		-543.45	-
	LESS 20% DISCOUNT		-	-812.94
			4,891.05	3,251.76
<u>SPECIAL NETT ITEMS</u>				
2	FRONT BUMPER SENSOR @\$220.00 (SN)	DENTED (1 PC ONLY)	440.00	220.00
4	FRONT RIVERTS @\$5.00 (SN)	NECESSARY	20.00	20.00
1	SET FRONT NO PLATE (EMBOSS)+HOLDER (SN)	SERVICEABLE	55.00	-
			515.00	240.00
<u>LABOUR</u>				
	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION.		55.00	20.00
	TO REPLACE FRT SENSOR & CHECK SENSOR WIRING.		120.00	60.00
	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.	NOT NECESSARY	120.00	-
	TO COMPUTERISE WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-

Report Ref No. CC6/FCI20011887/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR,PANEL BEAT,RE-STRAIGHTEN ON FRT SUPPORT PANEL,LABOUR TO REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		700.00	300.00
	TO PUTTY,PRIMER & SPRAY PAINT ON FRT BUMPER,FRT SENSOR,FRT RADIATOR TOP PANEL,RIGHT FRT AFFECTED FENDER & FRT AFFECTED BONNET USING 2K PAINT.		1,200.00	400.00
			2,315.00	780.00
GRAND TOTAL			7,721.05	4,271.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC6/FCI20011887/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 9527Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLN 9527Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

