



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 7296Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	798.50	798.50
1	REAR BUMPER SIDE LH	DENTED	195.00	195.00
1	REAR BUMPER SIDE RETAINER LH	BENT	17.50	17.50
1	REAR BUMPER REFLECTOR LH	CRACKED	148.50	148.50
1	TAILLAMP LH	CRACKED	468.50	468.50
1	REAR END PANEL	TO REPAIR SEE LABOUR	411.90	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	885.10	-
1	REAR FENDER PROTECTOR LH	TORN	180.10	180.10
1	REAR AIR VENT LH	CRACKED	28.00	28.00
1	SET REAR REVERSE SENSOR	SERVICEABLE	280.00	-
	LESS 20% DISCOUNT		-	-367.22
			3,413.10	1,468.88
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO RESET & REPROGRAMME SYSTEM.		80.00	50.00
	TO DISMANTLE & REFIX UPHOLSTERY CUSHION.		150.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR FENDER LH.		800.00	550.00
	TO PUTTY & SPRAY PAINTING.		800.00	600.00
			2,040.00	1,350.00
	<b>GRAND TOTAL</b>		<b>5,453.10</b>	<b>2,818.88</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,818.88</b>

Report Ref No. CS/TP20011897/Uqf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.