

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 8228A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED / CUT	2,150.54	2,150.54
1	REAR BUMPER REFLECTOR	DAMAGED	82.26	82.26
1	REAR BUMPER SIDE CHROME	AFFECTED	118.48	118.48
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	1,180.82	-
2	REAR BUMPER DISTANCE SENSOR	MALFUNCTION	357.50	178.75
2	REAR BUMPER DISTANCE SENSOR SPACER	NECESSARY	14.82	14.82
1	REAR BUMPER SIDE MOUNT	DAMAGED	72.86	72.86
1	TAIL PIPE COVER	TO REPAIR SEE LABOUR	790.22	-
1	TAIL PIPE COVER BRACKET	TO REPAIR SEE LABOUR	79.82	-
1	TAILLAMP RH	SERVICEABLE	1,034.20	-
	LESS 10% DISCOUNT		-	-261.77
			5,881.52	2,355.94
	<u>LABOUR</u>			
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF TAIL PIPE COVER BRACKET.		720.00	300.00
	SUPPLY PAINT MATERIAL AND TO RESPRAY REPLACED AND AFFECTED PANELS.		700.00	300.00
	TO CHECK ELECTRICAL COMPONENTS FOR PROPER FUNCTION.		80.00	30.00
	DIAGNOSTIC TEST, TO CHECK AND RESET MEMORY TO SPECIFICATIONS.		250.00	150.00
			1,750.00	780.00
	GRAND TOTAL		7,631.52	3,135.94

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/AIG20010743/T1vf3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Automotive Assessor Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.