

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20011901/ESD3E2

Date: 18/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993767		
Claimant Vehicle No :	SLS963D	Insured Vehicle No :	SLB3996D		
Date of Loss:	31/10/2020	Nature of Claim:	TP	Claim No:	9762406540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS963D	Engine No:	G4FGHU621379
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU537969
Reg. Date:	07/09/2017 (Man. Year: 2017)	Odometer:	49269 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/11/2020		
Date Inspected:	02/11/2020	Inspected At:	25 Kaki Bukit Road 4 #06-46 Synergy Repairer : Triple-t Automotive (HQ)
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1		*FRT BUMPER	Broken	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
8	1		*FRT BUMPER INNER TOP BRACKET	Broken	0.00 F	*- F
9	1		*FRT GRILLE	Broken	0.00 F	*- F
10	1		*REAR BUMPER	Dented	0.00 F	*- F
11	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
12	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
13	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
14	2		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
15	1		*REAR BUMPER LOWER SPOILER	Dented	0.00 F	*- F
16	1		*REVERSE SENSOR	Broken	0.00 F	*- F
17	1		*REAR END PANEL	Dented	0.00 F	*- F
18	1		*REAR END PANEL TOP GARNISH	Crushed	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >