

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20011902/KVD3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant
Vehicle No : SCL9119J

Insured Vehicle No : SLW3406E

Date of Loss: 27/10/2020

Nature of Claim: TP

Claim No: 630311

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCL9119J**

Make & Model: RENAULT FLUENCE, 1.5 D DCI 110 (A)

Engine No: K9KN837R005022

Reg. Date: 31/03/2016 (Man. Year: 2015)

Chassis No: VF1LZLF0E54828303

Colour: Metallic Grey

Odometer: 87094 km

Engine Capacity: 1461 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R17

Rear Tyre Size:

205/55R17

Front Left Side: Yokohama 7 mm

Rear Left Side:

Yokohama 7 mm

Front Right Side: Yokohama 7 mm

Rear Right Side:

Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,941.00	5,641.47	6,299.53	52.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,580.00	2,350.00	59.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	15,871.00	7,221.47	8,649.53	54.50
Approved Total (Overridden) (\$)		5,750.00		
(\$)	15,871.00	5,750.00	10,121.00	63.77
+ GST 7.00/7.00% (\$)	1,110.97	402.50	708.47	63.77
Nett Amount (\$)	16,981.97	6,152.50	10,829.47	63.77

INSPECTION

Date of Assignment: 02/11/2020

Date Inspected: 02/11/2020 Inspected At:

BLK 13 SIN MENG IND. EST.

SECTION B, #01-39

SINGAPORE 575657

REPAIRER: AERO GARAGE PTE

LTD

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2020)
Parts:	143	RENAULT FLUENCE 1.5 D DCI 110 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCL9119J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	1,830.00 F	*1,471.30 FL
2	1		*REAR DOOR OUTER HANDLE LH	Broken	240.00 F	*240.00 FL
3	1		*REAR DOOR LOCK LH	Dented	580.00 F	*420.00 FL
4	2		*REAR DOOR HINGES LH	Repair	190.00 F	*- FL
5	1		*REAR DOOR INNER HANDLE LH	Serviceable	102.00 F	*- FL
6	1		*REAR DOOR WEATHERSTRIP LH	Serviceable	190.00 F	*- FL
7	1		*REAR DOOR INNER TRIM LH	Mtg Cracked	1,430.00 F	*865.00 FL
8	1		*REAR DOOR REGULATOR LH	Distorted/Jammed	880.00 F	*680.00 FL
9	1		*REAR DOOR WINDSCREEN MOULDING LH	Necessary	120.00 F	*120.00 FL
10	1		*REAR DOOR PILLAR LH	Bent	170.00 F	*170.00 FL
11	1		*TAILLAMP LH	Cracked	2,019.00 F	*552.00 FL
12	1		*REAR FENDER LH	Bent	2,880.00 F	*1,750.00 FL
13	1		*REAR FENDER INNER SHIELD LH	Serviceable	340.00 F	*- FL
14	1		*REAR FENDER INNER TRIM LH	Serviceable	970.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,941.00	6,268.30
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	626.83
Total Parts (\$\$)	11,941.00	5,641.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	2,000.00	800.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
3	TO REMOVE,REPLACE REAR DOOR AND FENDER FITTINGS TO FACILITATE REPAIR	New	350.00	60.00
4	TO REMOVE,REPLACE REAR CUSHION AND REAR WINDSCREEN GLASS	New	300.00	200.00
5	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
Gross Labour Cost (\$\$)			3,930.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >