

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0124-20-TCA

24 August 2020

ACCIDENT VEHICLE SURVEY REPORT

CHH Construction System Pte Ltd
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	GBD2894D	Odometer:	180392km
Make & Model:	Nissan Cabstar 3/0 5M/T	Colour:	White
Chassis number:	JN1SC2F24Z0856245	Date of accident:	02/05/2019
Year of Regn.:	22/08/2014	Date inspected:	10/05/2019
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	17/05/2019

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	4mm/Othsu	4mm/Othsu	195R15
Rear:x2	2mm/Hifly	2mm/Hifly	155R13

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON BLOWER ASSY	1	fractured/shorted	1,030.70	1,030.70
AIRCON BLOWER PIPE	1	reuse	148.90	0.00
FRONT BUMPER	1	bent	1,155.30	1,155.30
FRONT BUMPER INNER BRACKET	1	bent	47.50	47.50
FRONT CORNER PANEL L/R	2	fractured	240.60	240.60
FRONT GRILLE	1	fractured	578.90	578.90
FRONT GRILLE 'LOGO' EMBLEM	1	necessary	55.30	55.30
FRONT GRILLE CENTER BRACKET	1	bent	48.00	48.00
FRONT HEADLAMP L/R	2	fractured	964.00	964.00
FRONT HEADLAMP LOWER GARNISH L/R	2	fractured	150.80	150.80
FRONT LH SIDE MIRROR (ROUND)	1	abraded	98.00	98.00
FRONT LH SIDE MIRROR (SQUARE)	1	abraded	128.00	128.00
FRONT LH SIDE MIRROR BRACKET	1	bent	207.50	207.50
FRONT LH SIDE MIRROR BRACKET COVER	1	fractured	59.00	59.00
FRONT LH SIDE MIRROR GARNISH	1	fractured	59.00	59.00
FRONT LH SIDE MIRROR GARNISH TOP COVER	1	fractured	38.00	38.00
FRONT PANEL	1	buckled	1,583.70	1,583.70
FRONT PANEL 'CABSTAR' EMBLEM	1	necessary	55.10	55.10
FRONT RH SIDE MIRROR	1	abraded	120.80	120.80
FRONT RH SIDE MIRROR BRACKET	1	bent	105.70	105.70
FRONT RH SIDE MIRROR BRACKET COVER	1	fractured	38.00	38.00
FRONT RH SIDE MIRROR GARNISH	1	fractured	48.00	48.00
FRONT RH SIDE MIRROR GARNISH TOP COVER	1	fractured	38.00	38.00
FRONT WINDSCREEN	1	cracked	819.90	819.90
FRONT WINDSCREEN LOWER MOULDING	1	necessary	64.30	64.30
FRONT WINDSCREEN MOULDING L/R	2	necessary	128.60	128.60
FRONT WINDSCREEN TOP MOULDING	1	necessary	103.50	103.50
FRONT WIPER ARM COVER L/R	2	fractured	37.60	37.60
FRONT WIPER LINK	1	bent	230.40	230.40
FRONT WIPER MOTOR	1	reuse	583.20	0.00
FRONT WIPER MOTOR ARM L/R	2	L-bent	89.30	44.65
FRONT WIPER PANEL	1	buckled	503.00	503.00
Subtotal before discount			S\$ 9,558.60	S\$ 8,781.85
Percentage discount 10% and 10%			S\$ 955.86	S\$ 878.19
Sub-total 1			S\$ 8,602.74	S\$ 7,903.67

FRONT BUMPER CLIPS - SET	1	necessary	100.00	100.00
FRONT BUMPER NUMBER PLATE	1	reuse	25.00	0.00
FRONT CORNER PANEL CLIPS L/R - SET	2	necessary	60.00	60.00
FRONT GRILLE CLIPS - SET	1	necessary	50.00	50.00
FRONT HEADLAMP CLIPS L/R - SET	2	necessary	80.00	80.00
FRONT LH SIDE MIRROR GARNISH CLIPS - SET	1	necessary	30.00	30.00
FRONT RH SIDE MIRROR GARNISH CLIPS - SET	1	necessary	30.00	30.00
FRONT WINDSCREEN E.R.P BRACKET	1	necessary	50.00	50.00
FRONT WINDSCREEN SEALANT	1	necessary	100.00	100.00
Subtotal before discount			S\$ 525.00	S\$ 500.00
Sub-total 2			S\$ 525.00	S\$ 500.00
Parts-total			S\$ 9,127.74	S\$ 8,403.67

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	140.00	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	120.00	60.00
To remove, change windscreen. (Front)	150.00	120.00
To remove, reinstall dashboard fascia, meter reading and etc. (to FR)	400.00	250.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,800.00	1,500.00
To apply anti-rust chemical on repaired and replaced panel.	120.00	60.00
Labour Total		S\$ 4,130.00 S\$ 3,110.00
Parts & Labour Total		S\$ 13,257.74 S\$ 11,513.67

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 9,800.00
and the recommended number of working days for the repairs is within 9 day(s).**


B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

























Report No: 0124-20-TCA

24 August 2020

ACCIDENT VEHICLE SURVEY REPORT

CHH Construction System I
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	GBD2894D	<i>Odometer:</i>	180392km
<i>Make & Model:</i>	Nissan Cabstar 3/0 5M/T	<i>Colour:</i>	White
<i>Chassis number:</i>	JN1SC2F24Z0856245	<i>Date of accident:</i>	02/05/2019
<i>Year of Regn.:</i>	22/08/2014	<i>Date inspected:</i>	10/05/2019
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	17/05/2019

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.







