Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/AIG20011908/NVF3Q2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #07-16 06/04/2021 Date: Singapore 079120

REFERENCE

Policy No: Insured/Claimant: MUHAMMAD ZAHID BIN AB WAHID 1800155743

Date of Loss: 26/10/2020 Nature of Claim: OD Claim No: 7083591673SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN8844G**

Make & Model: HONDA ADV750, 745cc ABS AUTO RC88E6302872 Engine No: Reg. Date: 24/12/2018 (Man. Year: 2018) Chassis No: JH2RC95A7KK201106

Colour: White Odometer: 20757 km

Engine Capacity: 745 cc

Market Value/New Car

S\$25,000.00 Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Rear Tyre Size: Front Tyre Size: 120/70 R17 160/60 R15 Rear Left Side: Front Left Side: Bridgestone 3 mm Bridgestone 4 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,634.20	3,282.60	5,351.60	61.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	550.00	1,580.00	74.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,764.20	3,832.60	6,931.60	64.39
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	10,014.20	3,082.60	6,931.60	69.22
+ GST 7.00/7.00% (S\$)	700.99	215.78	485.21	69.22
Nett Amount (S\$)	10,715.19	3,298.38	7,416.81	69.22

INSPECTION

Date of Assignment: 02/11/2020

Bike Production Pte Ltd (HQ) Date Inspected: 03/11/2020 Inspected At:

610 SERANGOON ROAD

Singapore 218216

Estimated Period of Repair: 2.0 days

Muhammad Nazril Bin Abdullah Manager: VERON CHEN Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Please be informed that owner withdraw OD claim

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$3,794.40 NETT) Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT MUDGUARD	Scratched	385.00 FL	*385.00 FL	
2	1		*FRONT LEFT FORK ASSY	*Check	1,388.00 FL	*- FL	
3	1		*FRONT RIGHT FORK ASSY	*Check	1,388.00 FL	*- FL	
4	1		*STEERING STEM	*Check	485.00 FL	*- FL	
5	2		*STEERING STEM BEARING	*Check	90.00 FL	*- FL	
6	1		*FRONT WHEEL AXLE	Serviceable	188.00 FL	*- FL	
7	1		*FRONT BRAKE DISK LEFT	Serviceable	460.00 FL	*- FL	
8	1		*FRONT BRAKE DISK RIGHT	Serviceable	460.00 FL	*- FL	
9	1		*FRONT WINDSHIELD	Missing	450.00 FL	*450.00 FL	
10	4		*WINDSHIELD NUT	*Check	40.00 FL	*- FL	
11	4		*WINDSHIELD SCREW	*Check	40.00 FL	*- FL	
12	2		*FRONT WINDSHIELD COVER	*Check	280.00 FL	*- FL	
13	1		*HEAD LIGHT PROTECTOR	Missing	75.00 FL	*75.00 FL	
14	1		*LEFT SIDE WIND DEFLECTOR	Missing	185.00 FL	*185.00 FL	
15	1		*LEFT SIDE FAIRING ASSY UPPER	Scratched	550.00 FL	*550.00 FL	
16	1		*LEFT SIDE FAIRING BLACK COVER	Scratched	245.00 FL	*245.00 FL	
17	1		*LEFT SIDE CRASH BAR	Scratched	395.00 FL	*395.00 FL	
18	1		*STEERING HANDLE	*Check	305.00 FL	*- FL	
19	1		*LEFT HANDGUARD	Cracked	214.00 FL	*214.00 FL	
20	1		*LEFT REAR COVER	Scratched	485.00 FL	*485.00 FL	
21	1		*REAR MUDGUARD ASSY	Cracked	485.00 FL	*485.00 FL	
22	1		*REAR NUMBER PLATE LAMP	Deformed	145.00 FL	*145.00 FL	
23	1		*FRONT SPORT RIM	Serviceable	485.00 FS	*-FS	
24	1		*BOX RACK	Serviceable	255.00 FS	*-FS	
25	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS	
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.				
				Sub Total (S\$)	9,508.00	3,644.00	
	- List Item Discount on L Items 10.00/10.00% (S\$)				873.80	361.40	
				Total Parts (S\$)	8,634.20	3,282.60	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING CHARGES.	New	120.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.	New	800.00	300.00
3	TO REPLACE AND BALANCE FRONT WHEEL RIM.	New	150.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	. New	380.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES. (*Check)	New	180.00	0.00
6	DECALS FULL WRAP.	New	500.00	250.00
	Gross Labour Cost (S\$)		2,130.00	550.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >